





Exhibit G--Grove with buildable area  
Appeal of two short plats:  
Avalon East : SUB14-01032  
Avalon West: SUB14-01033

# AVALON EAST - EAST

PORTION OF SE 1/4 OF SEC 33, TWP 26N, RGE 5E, WM

Subdivision  
City of Kirkland

FILE NO:

**LEGEND**

- FOUND CONCRETE MONUMENT
- SET 1/2" REBAR/CAP #40524
- FOUND 1/2" REBAR/CAP AS NOTED
- × SET AS NOTED
- UTILITY POLE
- ← UTILITY POLE WITH LUMINARE
- POWER METER
- ← GUY ANCHOR
- WATER METER
- ◇ HYDRANT
- WATER VALVE
- CATCH BASIN
- ⊙ SANITARY SEWER MANHOLE
- GAS VALVE
- GAS METER
- W- APPROX. WATER LINE LOCATION
- S- APPROX. SANITARY SEWER LINE LOCATION
- OH- APPROX. OVERHEAD UTILITY LINE LOCATION
- (M) MEASURED DIMENSION
- (C) CALCULATED DIMENSION
- (D) DECIDUOUS TREE
- (C) CONIFEROUS TREE

**CONTROL LEGEND**

- ⊙ FOUND 4" x 4" CONCRETE MONUMENT WITH TACK IN LEAD IN CASE DOWN 0.60'
- ⊙ FOUND CONCRETE MONUMENT WITH TACK IN LEAD IN CASE DOWN 0.40'
- ⊙ FOUND CONCRETE MONUMENT WITH TACK IN LEAD IN CASE DOWN 0.40'
- ⊙ FOUND CONCRETE MONUMENT WITH BRASS TACK IN LEAD IN CASE DOWN 0.40'
- ⊙ FOUND 4" x 4" CONCRETE MONUMENT WITH 3" BRASS DISK WITH PUNCH IN CASE DOWN 0.60'
- ⊙ FOUND 4" x 4" CONCRETE MONUMENT WITH 2" BRASS DISK WITH PUNCH IN CASE DOWN 0.40'
- ⊙ SET 1/2" REBAR/CAP #40524 AT 0.30' OFFSET TO THE EAST. PROPERTY CORNER IS THE FENCE POST
- ⊙ FOUND 1/2" REBAR/CAP #14490 WITH TACK AT CALCULATED POSITION
- ⊙ FOUND 1/2" REBAR/CAP #40524 AT CALCULATED POSITION

**ZONING**

RSX 7.2

**BASIS OF BEARINGS**

NORTH ALONG THE MONUMENTED CENTER LINE OF 128TH AVENUE NORTHEAST.

**DATUM**

NAVD88  
DESIGNATION: RED48  
DB ID: 43315  
DESCRIPTION: BRASS DISK IN CONCRETE STAMPED "CITY OF REDMOND BM 48 C.O.R."  
LOCATION: IN THE SOUTHEAST ANGLE OF THE INTERSECTION OF NORTHEAST 104TH STREET AND 132ND AVENUE NORTHEAST.  
ELEVATION: 334.247

**REFERENCES**

- LEE STREET SHORT PLAT RECORDED IN VOLUME 209,
- PLAT OF H.C. PETTIT'S ALDER GROVE RECORDED IN VOLUME 21 OF PLATS, PAGE 83, RECORDS OF KING COUNTY, WASHINGTON.

**NOTES**

- INSTRUMENTATION FOR THIS SURVEY WAS A SOKKIA 530R TOTAL STATION.
- PROCEDURES USED WERE FIELD TRAVERSE, MEETING OR EXCEEDING STANDARDS SET BY WAC 332-130-090.
- ALL UTILITIES SHOWN WERE DERIVED FROM PHYSICAL LOCATIONS ON THE GROUND SURFACE AT TIME OF SURVEY. CONTRACTOR TO VERIFY PRIOR TO ANY EXCAVATION.
- THIS SURVEY HAS BEEN PREPARED FOR THE EXCLUSIVE USE OF PARTIES WHOSE NAMES APPEAR HEREON ONLY, AND DOES NOT EXTEND TO ANY UNNAMED THIRD PARTIES WITHOUT EXPRESS RECERTIFICATION BY THE LAND SURVEYOR.
- BOUNDARY LINES SHOWN REPRESENT DEED LOCATIONS, OWNERSHIP LINES MAY VARY. NO GUARANTEE OF OWNERSHIP IS EXPRESSED OR IMPLIED.

**LEGAL DESCRIPTION**

THE EAST 150 FEET OF LOT 17, BLOCK 4, H.C. PETTIT'S ALDER GROVE, AN ADDITION TO KIRKLAND, ACCORDING TO THE PLAT THEREOF, RECORDED IN VOLUME 21 OF PLATS, PAGE 83, RECORDS OF KING COUNTY, WASHINGTON, EXCEPT THE NORTH 5 FEET; AND EXCEPT THE SOUTH 31.66 FEET THEREOF.

**SURVEYOR'S CERTIFICATE**

This map correctly represents a survey, made by me or under my direction, in conformance with the requirements of the Survey Recording Act at the request of Merit Homes, Inc. in February, 2014.

Surveyor Jim R. Watkins  
Certificate No. 40524



**PRELIMINARY SUBDIVISION**  
FOR

MERIT HOMES, INC.

SCALE: 1" = 20'  
DATE: 10/23/2014


JOB NO.: 14007



**Allied Land Surveying, Inc.**  
2312 168th Street Southeast  
Bothell, Washington 98012  
(P) 425-482-0223 (F) 425-482-0224

Trees 10-13

approximate  
diplines of the  
grove. The diplines  
per the arborist  
report is the limit of  
disturbance.





TO: Josh Lysen, Vice President Merit Homes  
JOB SITE: Avalon East & West - 10633 128<sup>th</sup> Ave NE, Kirkland, WA 98033  
SUBJECT: Tree Inventory & Assessment  
DATE: March 3, 2014; Revised May 27, 2014  
PREPARED BY: Sean Dugan,  
Registered Consulting Arborist #457  
ISA Certified Board Certified Master Arborist PN-5459B  
ISA Qualified Tree Risk Assessor

---

## Contents

*Summary*  
*Assignment & Scope of Report*  
*Methods*  
*Observations and Discussion*  
*Recommendations*  
*Glossary*  
*References*  
*Appendix A – Assumptions & Limiting Conditions*  
*Appendix B – Site Survey with Tree Locations*  
*Attachments:*  
*Table of Trees*

## Summary

I identified nineteen (19) significant size trees existing on the job site. Nine (9) of the trees are not viable due to poor health and/or non-viable structure. The total square footage of the two areas is 27,301 square feet. The Kirkland Zoning Code (95.33) requires a minimum tree density of 18.9 tree credits. I calculated the tree density credits for the remaining ten (10) trees to be 51 credits. Site development plans will need to be created to determine which trees can be preserved.

Two (2) trees on adjacent properties to the southwest and northeast have canopies that overhang the job site. These trees are unlikely to be negatively impacted due to being located far from the job site.

## Assignment & Scope of Report

This report outlines the site inspection by Sean Dugan, of Tree Solutions Inc., on February 18, 2014. I was asked to conduct a site visit to inventory all significant trees with descriptions of species, diameter size, health and structural condition, limits of disturbance, drip line radius, proposed action, tree credit values and notes for each tree. I was asked to develop a formal arborist report addressing city of Kirkland requirements for tree preservation.

Included in the report are observations from the site located at 10633 128<sup>th</sup> Ave NE, discussion, and recommendations. Josh Lysen, Vice President of Merit Homes, requested these services to acquire information for project planning in accordance with requirements set by the city of Kirkland.

#### Limits of Assignment

Unless stated otherwise: 1) information contained in this report covers only those trees that were examined and reflects the condition of those trees at the time of inspection; and 2) the inspection is limited to visual examination of the subject trees without dissection, excavation, probing, climbing, or coring unless explicitly specified. There is no warranty or guarantee, expressed or implied, that problems or deficiencies of the subject trees may not arise in the future.

I did not have permission to access the adjacent properties. Additional Assumptions and Limiting Conditions can be found in Appendix A.

#### **Methods**

I was provided with a site survey showing tree locations, which can be found in Appendix B. Numbers on the site survey correspond to those in the attached Table of Trees. Trees on adjacent properties with overhanging canopies are labeled on the survey using letters A and B. Measurements provided for these two trees are estimates as I did not have permission to access those sites.

I measured the diameter of each tree at standard height (DSH), typically 54-inches above grade. For multi-stemmed trees I calculated the equivalent single-stem equivalent diameter using the Guide to Trunk Area outlined in the Guide for Plant Appraisal (9<sup>th</sup> Edition).

I evaluated tree health and structure utilizing visual tree assessment (VTA) methods. The basis behind VTA is the identification of symptoms, which the tree produces in reaction to a weak spot or area of mechanical stress. Trees react to mechanical and physiological stresses by growing more vigorously to re-enforce weak areas, while depriving less stressed parts. (Mattheck & Breloer 1994) Understanding uniform stress allows me to make informed judgments about the condition of a tree.

#### **Observations & Discussion**

##### The Site

The site is comprised of two areas running east and west. The total square footage of both lots is 27,301 square feet. The lots are located in a residential neighborhood in the city of Kirkland. There are no environmentally critical areas or sensitive areas listed for the property.

The west lot is undeveloped and measured to be 14,104 square feet in size. The topography of the site is generally flat. The lot contains two of the nineteen significant trees inventoried.

The east lot is developed with an existing single family structure. The total area of this lot measures 13,197 square feet in size. The topography of this site is generally flat. There are seventeen significant-sized trees.

The adjacent site trees are located to the northeast and the southwest. Only a small portion of the canopies overhang the job site. The trees stand sufficiently away from the job site and the potential for them to be negatively impacted by proposed site development is very low.

The Trees

Nineteen (19) significant-sized trees stand on site. Tree species include Douglas-fir (*Pseudotsuga menziesii*), Japanese maple (*Acer palmatum*), Vine maple (*Acer circinatum*), Flowering dogwood (*Cornus florida*), Black pine (*Pinus nigra*), Western red cedar (*Thuja plicata*), and Western hemlock (*Tsuga heterophylla*) trees. Information specific to each tree can be found in the attached Table of Trees.

Ten of the trees I assessed are potentially viable and retention will be based on the site development plans.

The east and southeast portion of this site has a stand of Douglas-fir trees that are located in the front property of the existing dwelling. Due to the location, the City considers these to be high retention value trees. Unfortunately, it is my opinion that these are poor candidates for retention.

All of these trees have been topped in the past and the reiterative leads are approximately 40 to 60 feet tall. Several of the leads are poorly structured and are showing symptoms that indicate decay possibly exists at the point of the topping. (See Figure 1)



Figure 1. View looking southwest at trees 5, 6 and 7; white arrows point to the past topping cuts.

Each of the Douglas-fir trees in the stand currently present a moderate level of risk to the surrounding targets due to the potential for failure of the new leads. The likelihood of these failing will increase over time and so will the risk potential. Long-term management will be required to prevent a failure from contacting the future structure. Options for management are limited.

If any of the trees are removed I believe that it will have a negative impact on the adjacent trees. During my assessment, I was able to evaluate how the trees react in moderate wind gusts. Each tree relies on the adjacent trees for support during the bending moment of the leads. If a tree is removed, the support will go with it and there will be a greater likelihood of the remaining trees to fail.

#### Tree Density Credits

The Kirkland Zoning Code (95.33) requires tree density to satisfy 30 tree credits per acre. The property is 27,301 sq. ft., or 0.63 acres. Therefore, a tree density worth 18.9 tree credits ( $0.63 \times 30 = 18.9$ ) is required in order to meet the minimum requirement. Using viable trees, I calculated **51** tree credits are available on the site.

#### Adjacent Site Trees

Trees A and B are unlikely to be negatively impacted by site development.

#### **Recommendations**

- Create a site development plan that shows the location of all improvements, which can then be used to determine which trees can be retained.
- Plans should indicate basic tree protection measures for preserved trees on site and to assure minimal damage to the root systems of adjacent site trees.
- If 18.9 tree credits cannot be retained a supplemental tree planting plan will be required.
- Obtain all necessary permits and approval from the City prior to commencement of site work.

#### **Glossary**

**Basal (root) flare:** the rapid increase of diameter that occurs at the junction of the trunk and root crown, associated with stem and root tissues. (Dunster 1996)

**DBH or DSH:** diameter at breast or standard height; the diameter of the trunk measured 54 inches (4.5 feet) above grade (Matheny *et al.* 1998)

**drip line:** perimeter of the area under a tree delineated by the crown (Lilly 2001)

**ISA:** International Society of Arboriculture

#### **References**


- ANSI A300 (Part 1) – 2008 American National Standards Institute. American National Standard for Tree Care Operations: Tree, Shrub, and Other Woody Plant Maintenance: Standard Practices (Pruning). New York: Tree Care Industry Association, 2008.
- Dunster, Julian & Katherine. Dictionary of Natural Resource Management. Vancouver: UBC Press, 1996
- ISA Pacific Northwest Chapter. Tree Risk Assessment in Urban Areas and The Urban/Rural Interface (Course Manual). British Columbia, Canada, 2009
- Lilly, Sharon. Arborists' Certification Study Guide. Champaign, IL: The International Society of Arboriculture, 2001.
- Matheny, Nelda and James R. Clark. Trees and Development: A Technical Guide to Preservation of Trees During Land Development. Champaign, IL: International Society of Arboriculture, 1998.
- Mattheck, Claus and Helge Breloer, The Body Language of Trees.: A Handbook for Failure Analysis. London: HMSO, 1994

## Appendix A – Assumptions & Limiting Conditions

1. Consultant assumes that any legal description provided to Consultant is correct and that title to property is good and marketable. Consultant assumes no responsibility for legal matters. Consultant assumes all property appraised or evaluated is free and clear, and is under responsible ownership and competent management.
2. Consultant assumes that the property and its use do not violate applicable codes, ordinances, statutes or regulations.
3. Although Consultant has taken care to obtain all information from reliable sources and to verify the data insofar as possible, Consultant does not guarantee and is not responsible for the accuracy of information provided by others.
4. Client may not require Consultant to testify or attend court by reason of any report unless mutually satisfactory contractual arrangements are made, including payment of an additional fee for such Services as described in the Consulting Arborist Agreement.
5. Unless otherwise required by law, possession of this report does not imply right of publication or use for any purpose by any person other than the person to whom it is addressed, without the prior express written consent of the Consultant.
6. Unless otherwise required by law, no part of this report shall be conveyed by any person, including the Client, the public through advertising, public relations, news, sales or other media without the Consultant's prior express written consent.
7. This report and any values expressed herein represent the opinion of the Consultant, and the Consultant's fee is in no way contingent upon the reporting of a specific value, a stipulated result, the occurrence of a subsequent event or upon any finding to be reported.
8. Sketches, drawings and photographs in this report, being intended as visual aids, are not necessarily to scale and should not be construed as engineering or architectural reports or surveys. The reproduction of any information generated by architects, engineers or other consultants and any sketches, drawings or photographs is for the express purpose of coordination and ease of reference only. Inclusion of such information on any drawings or other documents does not constitute a representation by Consultant as to the sufficiency or accuracy of the information.
9. Unless otherwise agreed, (1) information contained in this report covers only the items examined and reflects the condition of the those items at the time of inspection; and (2) the inspection is limited to visual examination of accessible items without dissection, excavation, probing, climbing, or coring. Consultant makes no warranty or guarantee, express or implied, that the problems or deficiencies of the plans or property in question may not arise in the future.
10. Loss or alteration of any part of this Agreement invalidates the entire report.

10633 128<sup>th</sup> Ave. NE, Kirkland, WA  
March 3, 2014; Revised May 27, 2014

**Appendix B – Site Survey with Tree Locations**



**Attachments:**  
*Table of Trees*



**Table of Trees**  
**10633 128th Ave NE, Kirkland, WA 98033**

Exhibit H  
 Date of Inventory- 02.18.2014  
 Table Prepared- 02.20.2014  
 Table Revised- 05.21.2014

Tree #	Common/ Scientific Name	DSH (inches)	Mult DSH (inches)	Health Condition	Structural Condition	Limits of Disturbance	Viability	Risk	Proposed Action	Tree Credits	Notes
1	Vine maple/ <i>Acer circinatum</i>	9*	2, 4, 2, 4, 2.5, 2.5, 3, 1.5, 3, 3	Fair	Poor	Drip Line	No	Low	Remove - Structure	0	cluster, wide spread, no central lead, multiple dead leads
2	Douglas-fir/ <i>Pseudotsuga menziesii</i>	22.9		Good**	Fair-	Drip Line	No	Moderate/ High	Remove - Structure	0	topped at approx. 20 feet, 2 new central leads 40 feet tall- one subordinated with girdling branch
3	Douglas-fir/ <i>Pseudotsuga menziesii</i>	21.9		Good**	Fair	Drip Line	No	Moderate/ High	Remove - Structure	0	topped- new lead approximately 50 feet tall
4	Douglas-fir/ <i>Pseudotsuga menziesii</i>	26.9		Good**	Poor	Drip Line	No	Moderate/ High	Remove - Structure	0	topped, 2 new leads on 50 feet tall north & south side- south side looks to be damaged on compression side, bark pop at shear plain on north lead
5	Douglas-fir/ <i>Pseudotsuga menziesii</i>	22.5		Good**	Fair-	Drip Line	No	Moderate/ High	Remove - Structure	0	topped, 3 leads- 1 dead, tallest 50 feet tall, decayed stump, slight resin stream, stub cut, kink on top main lead
6	Douglas-fir/ <i>Pseudotsuga menziesii</i>	17		Good**	Poor	Drip Line	No	Moderate/ High	Remove - Structure	0	topped, new 40 foot lead- major stress riser
7	Douglas-fir/ <i>Pseudotsuga menziesii</i>	22.3		Good**	Fair	Drip Line	No	Moderate/ High	Remove - Structure	0	topped, growth 60 feet tall, ridge between new leads, U-shaped
8	Douglas-fir/ <i>Pseudotsuga menziesii</i>	17.2		Good**	Fair-	Drip Line	No	Moderate/ High	Remove - Structure	0	topped, 2 new leads 50 feet tall, fiber buckling on compression side of main new lead
9	Cherry/ <i>Prunus</i> spp.	7		Poor	Poor	Drip Line	No	Low	Remove - Health	0	over mature & in decline, diseased
10	Western hemlock/ <i>Tsuga heterophylla</i>	20		Good	Fair	Drip Line	Yes	Low		6	multiple tops-narrow angle of attachment



**Table of Trees**  
**10633 128th Ave NE, Kirkland, WA 98033**

Exhibit H  
 Date of Inventory- 02.18.2014  
 Table Prepared- 02.20.2014  
 Table Revised- 05.21.2014

11	Flowering dogwood/ <i>Cornus florida</i>	8.5		Fair	Fair	Drip Line	Yes	Low		1	canopy over whelmed by adjacent conifers, anthracnose
12	Western red cedar/ <i>Thuja plicata</i>	28		Good	Good	Drip Line	Yes	Low		10	
13	Japanese maple/ <i>Acer palmatum</i>	6.4*	5.5, 1, 1, 1, 2, 2	Fair	Fair	Drip Line	Yes	Low		1	multiple tops- narrow angle of attachment with included bark
14	Japanese maple/ <i>Acer palmatum</i>	6.9		Good	Good	Drip Line	Yes	Low	Remove - driveway & utilities	1	odd shrub form tree/bush, coral fungus, multiple pruning/ sheering events
15	Douglas-fir/ <i>Pseudotsuga menziesii</i>	32.5		Good	Good	Drip Line	Yes	Low	Remove - driveway & utilities	12	drive 2 west
16	Flowering dogwood/ <i>Cornus florida</i>	7.2		Good	Good	Drip Line	Yes	Low		1	slow grow
17	Black pine/ <i>Pinus nigra</i>	7.3		Fair	Fair	Drip Line	Yes	Low	Remove - driveway & utilities	1	sheared to small tree, topped in past
18	Douglas-fir/ <i>Pseudotsuga menziesii</i>	29.5		Good	Good	Drip Line	Yes	Low	Retain & Protect	10	hangers- crown cleaning needed if retained
19	Western hemlock/ <i>Tsuga heterophylla</i>	24.6		Fair	Fair	Drip Line	Yes	Moderate	Remove - utilities	8	unusual basal structure on west lower trunk- restricting growth, internal foliage sparse, significant debris in root zone
<b>Total Tree Credits</b>										51	
<b>Adjacent Site Trees</b>											
A	Western red cedar/ <i>Thuja plicata</i>	~10		Good	Good	Drip Line					canopy overhangs site by ten feet
B	Douglas-fir/ <i>Pseudotsuga menziesii</i>	~12+		Good	Good	Drip Line					canopy overhangs site by four feet

**Additional Notes:**

\*Single stem equivalent DSH calculated using Guide to Trunk Area; \*\*Internal decay likely

Tree Solutions, Inc.

1058 N. 39th St. Seattle, WA 98103