





# ORCAS MOON COTTAGES



VIEW 'B'



VIEW 'A'

## CONCEPTUAL RENDERINGS



VIEW 'C'



VIEW 'D'



VIEW 'E'



**BLUELINE**

CIVIL ENGINEERING • LAND USE PLANNING  
LANDSCAPE ARCHITECTURE





# Greenforest Incorporated



## Consulting Arborist

---

July 22, 2016

Robert Londo  
Orcas Moon, LLC  
PO Box 2710  
Redmond WA 98073

RE: Tree Inventory at Forbes Creek, TPN 3890100050 & 3890100055.

Dear:

You contacted me and contracted my services as a consulting arborist. My assignment is to tag and inspect the significant trees at the above referenced site. The purpose of this report is to establish the condition of the significant trees to satisfy City of Kirkland permit submittal requirements.

You provided me a topographic survey from Axis Survey & Mapping dated 5/10/16. I visited the site last week and visually inspected the trees indicated on the survey, which are the subject of this report.

The site has a northern aspect with variable topography. With the exception of 2 weeping willows, the subject trees are all native species, dominated by Bigleaf maple and Red alder. I inventoried 192 surveyed significant trees, plus (I annotated the survey with) an additional 5 significant trees (numbered A-E) not included initially. Three duplicate trees are identified at the end of the inventory.

#### TREE INSPECTION – Tree Health, Condition and Viability

Each tree was marked with a 1" x 3.5" aluminum tag indicating tree number prior to my inspection. I visually inspected each tree from the ground and rated both tree health and structure.

A tree's structure is distinct from its health. This inspection identifies what is visible with both. Structure is the way the tree is put together or constructed, and identifying

Robert Londo, Orcas Moon, LLC  
 RE: Tree Inventory at Forbes Creek, TPN 3890100050 & 3890100055.  
 July 22, 2016  
 Page 2 of 18

obvious defects can be helpful in determining if a tree is predisposed to failure. Tree health assesses disease, insect infestation and old age.

No invasive procedures were performed on any trees. The results of this inspection are based on what is visible at the time of the inspection.

The attached inventory summarizes my inspection results and provides the following information for each tree:

**Tree number** as shown on tag in the field.

**Tree Density Credit (TDC)** is assigned for each tree. The TDC for multiple-stemmed trees is calculated by summing the cross sectional area of each stem (DBH), and then converting to a single diameter.

**DBH** Stem diameter in inches measured 4.5 feet from the ground.

**Tree Species** Common name.

**Dripline** Average branch extension from the trunk as radius in feet.

**Health and Structure rating** ('1' indicates no visible health-related problems or structural defects, '2' indicates minor visible problems or defects that may require attention if the tree is retained, and '3' indicates significant visible problems or defects and tree removal is recommended.

**Visible defects** Obvious structural defects or diseases visible at time of inspection, which includes:

Asymmetric canopy– the tree has an asymmetric canopy from space and light competition from adjacent trees.

Branch dieback - Mature branches in canopy are dying/dead.

Crack – separation of wood fibers and predisposed to failure.

Dead – tree is dead.

Deadwood – Large and/or multiple dead branches throughout canopy.

Decay – process of wood degradation by microorganisms resulting in weak and defective structure.

Diseased – foliage and trunk/stems are diseased.

Dogleg in trunk – trunk with a bow or defective bend (90°) in trunk often half way of further up the trunk.

Robert Londo, Orcas Moon, LLC  
 RE: Tree Inventory at Forbes Creek, TPN 3890100050 & 3890100055.  
 July 22, 2016  
 Page 3 of 18

Double leader – the tree has multiple stem attachments, which may require maintenance or monitoring over time.  
 Included bark - Bark inclusion at attachment of multiple leaders and is preventing a wood-to-wood attachment  
 Insect Injury – active insect injury affecting tree health.  
 Ivy - Dense ivy prevents a thorough inspection, and other defects may be present.  
 Kretzschmaria fungus indicated internal wood decay.  
 Multiple leaders - the tree has multiple stem attachments, which may lead to tree failure and require maintenance or monitoring over time.  
 Previous failure – Tree trunk previously broken and defective.  
 Sweep in trunk – characterized by a leaning lower trunk and a more upright top.  
 Thinning Canopy – low foliage density may indicate stress, or early infection/declining health.  
 Stumpsprout- Tree previously cut at grade with multiple stems and potentially weak attachments.  
 Suppressed – tree crowded by larger adjacent trees; with defective structure and/or low vigor. Retain tree only as a grove tree, not stand-alone.  
 Sweep – tree leans away from adjacent trees. Characterized by a leaning lower trunk and a top that is more upright.  
 Topped – the tree is previously topped and has poor structure and/or stem decay.  
 Tree leans – Trunk has significant lean from vertical.  
 Tree suppressed - Tree is suppressed by adjacent tree canopies.  
 Trunk decay - Wood decay is visible in the trunk.  
 Wound/decay base of trunk - Open wound with visible decay in trunk.

**Viability** a determination by the arborist whether the tree is viable for retention.

Non-viable trees are indicated. Otherwise the tree is viable, but the tree's visible defects should be considered. Depending on the location of a non-viable tree to any site improvements, if the tree is out of range of a target, it might be retained as it can continue to contribute canopy cover and wildlife habitat.

Robert Londo, Orcas Moon, LLC  
 RE: Tree Inventory at Forbes Creek, TPN 3890100050 & 3890100055.  
 July 22, 2016  
 Page 4 of 18

#### REQUIRED TREE DENSITY & AVAILABLE TREE DENSITY CREDIT

Required tree density is calculated by multiplying the acreage of the lot by 30, which equals 213. ( $309,061 \div 43,560 = 7.1$ ) X 30 = 212.85, or 213 rounded.

	S. F. <sup>1</sup>	Acres
Lot A	143,218	3.29
Lot B	165,843	3.81
Total Area	309,061	7.10

The required tree density credit for this site = 213. The available tree density credits for specific trees are established in the attached inventory. The total available tree density credit for the surveyed trees equals 1,041.

NOTE: Tree density calculations do not apply to public trees. Trees shown within a ROW are assigned zero TDC.

If the calculated (retained) tree density is below the required minimum, you must indicate the type, size and location of the supplemental trees needed to meet the density requirement on a tree retention plan. Supplemental trees must be at least 6 feet tall if they are conifers or 2-inch caliper if they are deciduous or broadleaf evergreen. City may require more than the minimum TDC on any project.

This project is currently in the design phase. The following information will be provided later under separate scope and cover:

1. Limits of Disturbance.
2. Special instructions for work within critical root zones.
3. The impact of necessary tree removal to the remaining trees.
4. Timing and installation of tree protection measures.
5. Location and type of protection measures for trees.

#### LIMITATIONS AND USE OF THIS REPORT

This tree report establishes, via the most practical means available, the existing conditions of the trees on the subject property. Ratings for health and structure, as well as any recommendations are valid only through the development and construction

<sup>1</sup> <http://gismaps.kingcounty.gov/parcelviewer2/> (Accessed 7/22/2016)

Robert Londo, Orcas Moon, LLC  
RE: Tree Inventory at Forbes Creek, TPN 3890100050 & 3890100055.  
July 22, 2016  
Page 5 of 18

process. This report is based solely on what is readily visible and observable, without any invasive means.

There are several conditions that can affect a tree's condition that may be pre-existing and unable to be ascertained with a visual-only analysis. No attempt was made to determine the presence of hidden or concealed conditions which may contribute to the risk or failure potential of trees on the site. These conditions include root and stem (trunk) rot, internal cracks, structural defects or construction damage to roots, which may be hidden beneath the soil. Additionally, construction and post-construction circumstances can cause a relatively rapid deterioration of a tree's condition.

Thank you for your business.

Sincerely,

GreenForest, Inc.



By Favero Greenforest, M. S.

ISA Certified Arborist # PN -0143A  
ASCA Registered Consulting Arborist® #379  
ISA Tree Risk Assessment Qualified

#### Attachments

1. Assumptions and Limiting Conditions
2. Tree Inventory
3. Tree Survey Lot A
4. Tree Survey Lot B

Robert Londo, Orcas Moon, LLC  
RE: Tree Inventory at Forbes Creek, TPN 3890100050 & 3890100055.  
July 22, 2016  
Page 6 of 18

Attachment No. 1 - Assumptions & Limiting Conditions

1. A field examination of the site was made 7/19/2016. My observations and conclusions are as of that date.
2. Care has been taken to obtain all information from reliable sources. All data has been verified insofar as possible; however, the consultant/arborist can neither guarantee nor be responsible for the accuracy of information provided by others.
3. I am not a qualified land surveyor. Reasonable care was used to match the trees indicated on the sheets with those growing in the field.
4. Construction activities can significantly affect the condition of retained trees. All retained trees should be inspected after construction is completed, and then inspected regularly as part of routine maintenance.
5. Unless stated other wise: 1) information contained in this report covers only those trees that were examined and reflects the condition of those trees at the time of inspection; and 2) the inspection is limited to visual examination of the subject trees without dissection, excavation, probing, or coring. There is no warranty or guarantee, expressed or implied that problems or deficiencies of the subject tree may not arise in the future.
6. All trees possess the risk of failure. Trees can fail at any time, with or without obvious defects, and with or without applied stress. A complete evaluation of the potential for this (a) tree to fail requires excavation and examination of the base of the subject tree. Permission of the current property owner must be obtained before this work can be undertaken and the hazard evaluation completed.
7. The consultant/appraiser shall not be required to give testimony or to attend court by reason of this report unless subsequent contractual arrangements are made.
8. This report and any values/opinions expressed herein represent the opinion of the consultant/appraiser, and the consultant's/appraiser's fee is in no way contingent upon the reporting of a specified value, a stipulated result, the occurrence of a subsequent event, nor upon any finding to be reported.

Robert Londo, Orcas Moon, LLC

RE: Tree Inventory at Forbes Creek, TPN 3890100050 &amp; 3890100055.

July 22, 2016

Page 7 of 18

## Attachment No. 2 – Significant Tree Inventory

TREE No.	Tree Density Credit	DBH	Tree Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
20235	2	12"	Red alder	16'	1	2	Decline	
20236	14	36"	Weeping willow	35'	2	2	Diseased, ivy	
20237	2	12"	Red alder	18'	1	3	Upper trunk decay	NO
20238	1	10"	Red alder	12'	1	3	Trunk failure	NO
20239	1	10"	Red alder	14'	1	2	Asymmetric	
20240	1	8"	Red alder	0'	3	3	Covered in vines	NO
20241	1	10"	Red alder	14'	1	2	Asymmetric, vines	
20243	1	8"	Red alder	12'	1	2	Asymmetric	
20244	1	6"	Red alder	0'	3	3	Covered in vines	NO
20246	1	8"	Red alder	6'	1	3	Adjacent tree fell into it	NO
20247	1	10"	Red alder	14'	1	2	Asymmetric	
20249	1	6"	Red alder	6'	1	2	Suppressed	
20250	4	16"	Weeping willow	12'	1	3	Previous trunk failure	NO
20251	1	8"	Red alder	14'	1	2	Asymmetric	
20254	1	6"	Red alder	10'	1	2	Suppressed	
20256	1	8"	Red alder	10'	1	2	Asymmetric	
20257	1	8"	Red alder	14'	1	3	Asymmetric, trunk injury	NO
20258	1	8"	Red alder	14'	1	2	Lean, asymmetric	
20259	1	8"	Red alder	12'	1	2	Asymmetric, lean	
20260	1	10"	Red alder	16'	1	2	Asymmetric	



Robert Londo, Orcas Moon, LLC

RE: Tree Inventory at Forbes Creek, TPN 3890100050 &amp; 3890100055.

July 22, 2016

Page 8 of 18

TREE No.	Tree Density Credit	DBH	Tree Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
20261	1	6"	Red alder	12'	1	2	Suppressed	
20262	1	6"	Red alder	8'	1	2	Asymmetric	
20263	1	10"	Red alder	16'	1	2	Asymmetric	
20264	1	8"	Red alder	12'	1	1		
20265	1	8"	Red alder	14'	1	2	Asymmetric	
20266	1	6"	Red alder	6'	1	2	Suppressed	
20267	1	6"	Red alder	8'	1	2	Asymmetric	
20268	1	8"	Red alder	14'	1	2	Lean	
20269	1	6"	Red alder	8'	1	2	Suppressed	
20270	1	8"	Red alder	10'	1	1		
20271	1	10"	Red alder	14'	1	1		
20272	1	8"	Western red-cedar	10'	1	1		
20273	1	8"	Red alder	14'	1	2	Asymmetric	
20274	1	8"	Red alder	12'	1	2	Asymmetric	
20275	1	8"	Red alder	12'	1	2	Lean	
20276	1	8"	Red alder	14'	1	2	Suppressed	
20277	1	8"	Red alder	14'	1	2	Sweep	
20278	10	28"	Red alder	12'	2	3	Decline, decay	NO
20279	1	8"	Red alder	10'	1	1		
20280	1	6"	Red alder	10'	1	2	Lean	
20281	1	8"	Red alder	12'	1	1		
20283	2	12"	Red alder	12'	1	2	Asymmetric	



Robert Londo, Orcas Moon, LLC

RE: Tree Inventory at Forbes Creek, TPN 3890100050 &amp; 3890100055.

July 22, 2016

Page 9 of 18

TREE No.	Tree Density Credit	DBH	Tree Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
20286	1	6"	Red alder	8'	1	1		
20288	1	6"	Red alder	8'	2	1	Stem canker	
20292	5	18"	Bitter cherry	16'	1	2	Asymmetric	
20293	1	6"	Red alder	8'	1	3	Root failure	NO
20294	2	12"	Red alder	10'	3	3	Decline, vine, dying-nearly dead	NO
20296	18	22,40"	Bigleaf maple	35'	1	2	Soil heave	
20297	5	18"	Douglas-fir	16'	1	1		
20307	1	6"	Douglas-fir	8'	1	2	Suppressed	
20309	15	38"	Bigleaf maple	30'	1	3	Decay, <i>Kretzschmaria</i>	NO
20319	1	6"	Douglas-fir	6'	1	2	Suppressed	
20321	1	6"	Red alder	8'	1	1		
20324	2	12"	Douglas-fir	14'	1	1		
20349	11	22,20"	Bigleaf maple	30'	1	2	Double leader	
20350	12	10",18",18",16"	Bigleaf maple	20'	2	3	Decline, stump sprout, <i>Kretzschmaria</i>	NO
20351	0	20"	Bigleaf maple	20'	1	1		
20352	7	14,12,22"	Bigleaf maple	18'	1	2	Multiple leaders	
20353	12	14",16",18",18"	Bigleaf maple	25'	2	2	Decay, multiple leaders, chain embedded in trunk	
20354	5	18"	Bigleaf maple	16'	2	3	Decline, trunk decay, <i>Kretzschmaria</i>	NO
20355	7	10,14,14""	Bigleaf maple	16'	2	3	Decline, trunk decay, <i>Kretzschmaria</i>	NO
20356	8	24"	Bigleaf maple	18'	2	3	Decline, <i>Kretzschmaria</i>	NO
20357	3	14"	Douglas-fir	12'	1	2	Ivy	



Robert Londo, Orcas Moon, LLC

RE: Tree Inventory at Forbes Creek, TPN 3890100050 &amp; 3890100055.

July 22, 2016

Page 10 of 18

TREE No.	Tree Density Credit	DBH	Tree Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
20358	5	18"	Bitter cherry	12'	2	3	Decline, stem failure	NO
20359	1	6"	Douglas-fir	6'	1	2	Suppressed	
20360	7	22"	Red alder	16'	2	2	Decline, double leader	
20361	15	24",22",18",10"	Bigleaf maple	30'	1	2	Multiple leaders	
20362	7	10,14,14"	Western red-cedar	12'	1	1		
20363	13	24,24"	Bigleaf maple	25'	1	2	Double leader	
20364	8	24"	Bigleaf maple	30'	1	1		
20366	21	38,40"	Black cottonwood	25'	1	2	Double leader	
20367	3	14"	Red alder	10'	1	3	Lean, ivy	NO
20368	1	10"	Red alder	12'	2	2	Decline, nearly dead	
20412	2	12"	Red alder	16'	1	1		
20413	1	8"	Red alder	14'	1	2	Asymmetric	
20414	1	8"	Red alder	14'	1	2	Asymmetric	
20415	1	10"	Red alder	14'	1	1		
20416	1	6,8"	Red alder	14'	1	2	Asymmetric, double leader, included bark	
20417	1	7"	Red alder	4'	1	1		
20418	1	10"	Red alder	14'	1	1		
20419	1	8"	Red alder	10'	1	2	Asymmetric	
20420	1	8"	Red alder	10'	1	2	Asymmetric	
20421	1	8"	Red alder	10'	1	2	Asymmetric	
20427	4	16"	Red alder	14'	2	3	Decline, deadwood	NO



Robert Londo, Orcas Moon, LLC

RE: Tree Inventory at Forbes Creek, TPN 3890100050 &amp; 3890100055.

July 22, 2016

Page 11 of 18

TREE No.	Tree Density Credit	DBH	Tree Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
20428	2	12"	Bigleaf maple	16'	1	2	Asymmetric	
20429	5	18"	Bigleaf maple	20'	2	1	Stunted upper foliage	
20447	20	18,20,24,28"	Bigleaf maple	25'	1	2	Multiple leaders	
20448	21	36,38"	Bigleaf maple	20'	1	2	Double leader	
20449	4	16"	Bigleaf maple	18'	1	1		
20450	21	52"	Black cottonwood	25'	1	2	Asymmetric, sweep	
20451	21	65"	Black cottonwood	25'	1	2	Asymmetric, sweep	
20452	18	44"	Black cottonwood	25'	1	2	Asymmetric, sweep	
20453	21	10,18,20,20,26,30"	Bigleaf maple	30'	1	3	Previous failure, multiple leaders, stump sprout	NO
20454	11	30"	Black cottonwood	25'	1	2	Asymmetric, sweet	
20456	9	26"	Black cottonwood	25'	1	2	Asymmetric, sweet	
20460	21	6,24,30,34"	Bigleaf maple	25'	1	2	Multiple leaders	
20470	4	16"	Bigleaf maple	14'	1	2	Trunk wound, deadwood	
20495	4	16"	Bigleaf maple	16'	1	1		
20528	4	16"	Bigleaf maple	18'	1	2	Asymmetric	
20530	1	8"	Douglas-fir	6'	1	2	Suppressed	
20532	5	18"	Bigleaf maple	18'	1	2	Deadwood, asymmetric	
20536	21	50"	Black cottonwood	30'	1	1		
20540	11	30"	Bigleaf maple	20'	1	2	Asymmetric	
20543	6	20"	Western red-cedar	14'	1	1		
20544	21	54"	Black cottonwood	20'	1	2	Sweep in trunk	



Robert Londo, Orcas Moon, LLC

RE: Tree Inventory at Forbes Creek, TPN 3890100050 &amp; 3890100055.

July 22, 2016

Page 12 of 18

TREE No.	Tree Density Credit	DBH	Tree Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
20545	11	18,16,16"	Bigleaf maple	20'	2	3	Stunted, trunk failure, stumpsprout	NO
20546	1	6"	Western red-cedar	8'	1	2	Suppressed	
20547	10	28"	Bigleaf maple	25'	1	2	Branch failure, asymmetric	
20548	3	14"	Western red-cedar	12'	1	2	Suppressed	
20549	2	12"	Western red-cedar	14'	1	2	Suppressed	
20550	8	24"	Bigleaf maple	18'	1	2	Asymmetric	
20551	5	18"	Bigleaf maple	16'	1	2	Seam in trunk	
20562	17	42"	Douglas-fir	20'	1	1		
20666	16	40"	Bigleaf maple	25'	1	2	Spiral cracks in trunk	
20667	4	16"	Western hemlock	16'	1	1		
20668	1	8"	Bigleaf maple	14'	1	3	Asymmetric, suppressed	NO
20674	16	32,22,10"	Bigleaf maple	30'	1	2	Multiple leaders	
20675	11	24,18"	Bigleaf maple	25'	2	2	Stunted foliage, stump sprout	
20678	21	2-20",18", 2-12",10", 26",34",16"	Bigleaf maple	25'	2	2	Stunted foliage, multiple leader, deadwood	
20679	1	10"	Douglas-fir	12'	1	2	Suppressed	
20682	8	24"	Douglas-fir	18'	1	1		
20683	7	22"	Bigleaf maple	18'	1	2	Asymmetric	
20684	8	24"	Western red-cedar	18'	1	2	Double leader	
20688	3	14"	Douglas-fir	16'	1	2	Dogleg, double leader	
20689	9	26"	Western red-cedar	16'	1	1		



Robert Londo, Orcas Moon, LLC

RE: Tree Inventory at Forbes Creek, TPN 3890100050 &amp; 3890100055.

July 22, 2016

Page 13 of 18

TREE No.	Tree Density Credit	DBH	Tree Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
20690	5	18"	Western red-cedar	16'	1	1		
20691	1	8"	Western red-cedar	8'	1	2	Asymmetric	
20693	1	10"	Red alder	14'	1	3	Lean	NO
20694	5	18"	Western red-cedar	12'	1	2	Sweep in trunk	
20695	4	16"	Western hemlock	14'	1	1		
20696	3	14"	Western red-cedar	12'	1	1		
20697	4	16"	Red alder	12'	1	3	Top of tree is dead	NO
20699	13	34"	Bigleaf maple	25'	1	2	Asymmetric	
20700	6	20"	Western red-cedar	14'	1	1		
20702	4	16"	Bigleaf maple	14'	1	1		
20703	1	8"	Western hemlock	10'	1	2	Suppressed	
20704	5	18"	Bigleaf maple	18'	1	2	Deadwood	
20709	8	24"	Bigleaf maple	16'	1	1		
20714	3	14"	Bigleaf maple	16'	1	3	Asymmetric, trunk decay	NO
20715	4	16"	Bigleaf maple	16'	1	2	Asymmetric	
20716	10	28"	Bigleaf maple	20'	1	1		
20717	2	12"	Western hemlock	14'	1	2	Suppressed	
20718	6	20"	Bigleaf maple	18'	1	1		
20719	7	22"	Bigleaf maple	18'	1	2	Asymmetric	
20720	1	6"	Douglas-fir	8'	1	2	Suppressed	
20721	6	20"	Bigleaf maple	18'	1	3	Trunk decay	NO
20722	8	24"	Bigleaf maple	20'	1	2	Asymmetric	



Robert Londo, Orcas Moon, LLC

RE: Tree Inventory at Forbes Creek, TPN 3890100050 &amp; 3890100055.

July 22, 2016

Page 14 of 18

TREE No.	Tree Density Credit	DBH	Tree Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
20724	11	18,24"	Bigleaf maple	20'	1	3	Stumpsprout	NO
20726	4	16"	Bigleaf maple	18'	1	3	Dog leg, stumpsprout	NO
20727	2	12"	Bigleaf maple	16'	1	3	Asymmetric, lean	NO
20730	1	10"	Western red-cedar	12'	1	1		
20731	6	20"	Western red-cedar	16'	1	1		
20732	21	28,30,30,24"	Bigleaf maple	35'	1	2	Deadwood, failure, stumpsprout	
20733	3	8,12"	Bigleaf maple	16'	1	2	Asymmetric, stumpsprout	
20734	16	32,26"	Bigleaf maple	25'	1	3	Trunk decay, stumpsprout, Kretzschmaria	NO
20735	7	22"	Bigleaf maple	18'	1	2	Deadwood, asymmetric	
20736	4	16"	Bigleaf maple	18'	1	2	Asymmetric, stumpsprout	
20737	4	16"	Bigleaf maple	16'	1	3	Leaning in adjacent tree	NO
20738	3	6,14"	Bigleaf maple	18'	1	2	Stump sprout	
20739	6	20"	Bigleaf maple	20'	1	3	Stump sprout	NO
20740	5	18"	Bigleaf maple	16'	1	3	Dog leg, branch failure, stumpsprout	NO
20741	5	18"	Western red-cedar	16'	1	1		
20742	7	22"	Western red-cedar	16'	1	1		
20743	4	16"	Western red-cedar	14'	1	2	Growing against maple	
20744	4	16"	Bigleaf maple	16'	1	2	Previous branch failure, sweep in trunk	
20748	3	14"	Bigleaf maple	16'	1	2	Asymmetric	
20749	1	6"	Bigleaf maple	12'	1	3	Dog leg, trunk injury, stumpsprout	NO
20751	11	6,6,8,18,24"	Bigleaf maple	25'	2	3	Decline, decay, stumpsprout	NO



Robert Londo, Orcas Moon, LLC

RE: Tree Inventory at Forbes Creek, TPN 3890100050 &amp; 3890100055.

July 22, 2016

Page 15 of 18

TREE No.	Tree Density Credit	DBH	Tree Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
20780	4	16"	Bigleaf maple	18'	1	2	Dog leg in trunk	
20793	1	6"	Pacific dogwood	8'	1	2	Deadwood	
20807	3	14"	Western red-cedar	10'	1	2	Sweep in trunk	
20862	2	12"	Red alder	8'	2	3	Decline	NO
20864	4	16"	Red alder	14'	1	1		
20870	7	8,12,18"	Bigleaf maple	18'	1	3	Asymmetric, stumpsprout	NO
20934	0	6"	Red alder	8'	1	1		
20978	5	12,14"	Red alder	12'	2	3	Top failure	NO
20979	1	10"	Red alder	8'	2	3	Top of tree is dead	NO
20982	13	22,26"	Bigleaf maple	18'	1	2	Trunk decay	
20989	6	14,16"	Bigleaf maple	14'	1	2	Dogleg, asymmetric	
20990	5	18"	Scouler's willow	14'	1	3	Leaning trunk	NO
21020	1	10"	Red alder	14'	1	3	Trunk wound/decay	NO
21021	0	18"	Douglas-fir	16'	1	2	Topped for power lines	
21022	0	16"	Douglas-fir	16'	1	2	Topped for power lines	
21024	1	7"	Red alder	8'	2	3	Decline, decay	NO
21025	1	7"	Red alder	8'	2	3	Decline, decay	NO
21026	6	20"	Western red-cedar	14'	1	1		
21027	1	7"	Red alder	10'	2	2	Decline, decay	
21028	1	10"	Red alder	10'	1	1		
21029	0	6",12",14",16", 10",18",8"	Western red-cedar	16'	1	2	Stump sprout	



Robert Londo, Orcas Moon, LLC

RE: Tree Inventory at Forbes Creek, TPN 3890100050 & 3890100055.

July 22, 2016

Page 16 of 18


TREE No.	Tree Density Credit	DBH	Tree Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
22119	3	14"	Western hemlock	10'	1	3	Branch decline, spiral cracks in trunk	NO
22120	5	18"	Western red-cedar	14'	1	2	Asymmetric	
22121	5	18"	Western red-cedar	14'	1	2	Asymmetric	
A	1	8"	Douglas-fir	6'	1	1		
B	1	8"	Western red-cedar	6'	1	2	Sweep	
C	8	24"	Bigleaf maple	16'	1	3	Trunk decay	NO
D	20	48"	Black cottonwood	25'	1	1		
E	4	16"	Bigleaf maple	18'	1	3	Asymmetric, stumpsprout	NO
	1041							

The following trees are duplicates and not included in the above inventory.

20725	18"M	Duplicate of 20724
20692	24"C	Surveyed twice, same as 20689
20750	20"M	Duplicate of 20751



# BOUNDARY & TOPOGRAPHIC SURVEY



SEE SHEET 2

NE 1/4, SW 1/4, SEC. 32, TWP. 26N, RGE. 5E, W.M. CITY OF KIRKLAND, KING COUNTY, WASHINGTON

REV#	DESCRIPTION OF REVISION	DATE	BY
#1			
#2			
#3			
#4			
#5			
#6			
#7			

SURVEY  
FOR  
**LOTS A & B, LLA06-0026**

ROBERT P LONDO  
ORCAS MOON, LLC  
  
KIRKLAND, WA 98034



www.axismap.com	
JOB NO.	DATE
DRAWN BY	CHECKED BY
SCALE	SHEET
1" = 20'	1 OF 2

Robert Londo, Orcas Moon, LLC  
 RE: Tree Inventory at Forbes Creek, TPN 3890100050 & 3890100055.  
 Page 16 of 118  
 Attachment No. 4 - Tree Survey Lot B



# Greenforest Incorporated



## Consulting Arborist

TO: Robert Londo  
Orcas Moon, LLC  
PO Box 2710  
Redmond WA 98073

REFERENCE: Arborist Report

SITE ADDRESS: Forbes Creek, TPN 3890100050 & 3890100055.

DATE: November 20, 2017

PREPARED BY: Favero Greenforest, ISA Certified Arborist # PN -0143A  
ISA Tree Risk Assessment Qualified  
ASCA Registered Consulting Arborist® #379

---

This *arborist report* establishes the condition of the significant trees at the referenced site, and is to be used to satisfy City of Kirkland permit submittal requirements (Kirkland Zoning Code §95.30.4.c).

Last year you contracted my services to prepare a *significant tree inventory* of the regulated trees on the site as per KZC §95.30.4.a, which is incorporated into this report.

You provided me a topographic survey from Axis Survey & Mapping dated 5/10/16. I visited the site 7/19/16 and visually inspected the trees indicated on the survey, which are the subject of this report.

The site has a northern aspect with variable topography. With the exception of 2 weeping willows, the subject trees are all native species, dominated by Bigleaf maple and Red alder. I inventoried 192 surveyed significant trees, plus (I annotated the survey with) an additional 5 significant trees (numbered A-E) not included initially. Three duplicate trees are identified at the end of the inventory.

Robert Londo, Orcas Moon, LLC  
RE: Arborist Report at Forbes Creek, TPN 3890100050 & 3890100055.  
November 20, 2017  
Page 2 of 21

#### LIMITATIONS AND USE OF THIS REPORT

This tree report establishes, via the most practical means available, the existing conditions of the trees on the subject property. Ratings for health and structure, as well as any recommendations are valid only through the development and construction process. This report is based solely on what is readily visible and observable, without any invasive means.

There are several conditions that can affect a tree's condition that may be pre-existing and unable to be ascertained with a visual-only analysis. No attempt was made to determine the presence of hidden or concealed conditions which may contribute to the risk or failure potential of trees on the site. These conditions include root and stem (trunk) rot, internal cracks, structural defects or construction damage to roots, which may be hidden beneath the soil. Additionally, construction and post-construction circumstances can cause a relatively rapid deterioration of a tree's condition.

#### TREE INSPECTION – Tree Health, Condition and Viability

Each tree was marked with a 1" x 3.5" aluminum tag indicating tree number prior to my inspection. I visually inspected each tree from the ground and rated both tree health and structure.

A tree's structure is distinct from its health. This inspection identifies what is visible with both. Structure is the way the tree is put together or constructed, and identifying obvious defects can be helpful in determining if a tree is predisposed to failure. Tree health assesses disease, insect infestation and old age.

No invasive procedures were performed on any trees. The results of this inspection are based on what is visible at the time of the inspection.

The attached inventory summarizes my inspection results and provides the following information for each tree:

**Parcel** indicated general location of tree.

**Proposed action** identifies trees to be removed, saved, impacted and those that are non-viable.

**Tree Density Credit (TDC)** is assigned for each tree from table KZC 95.33.1 The TDC for multiple-stemmed trees is calculated using quadratic mean diameter.

**Retained TDC** tallies credits for retained trees. Native conifers are assigned 1.5 times credit.

Robert Londo, Orcas Moon, LLC  
 RE: Arborist Report at Forbes Creek, TPN 3890100050 & 3890100055.  
 November 20, 2017  
 Page 3 of 21

**Tree number** as shown on tag in the field.

**DBH** Stem diameter in inches measured 4.5 feet from the ground.

**Tree Species** Common name.

**Dripline** Average branch extension from the trunk as radius in feet.

**Health and Structure rating** '1' indicates no visible health-related problems or structural defects, '2' indicates minor visible problems or defects that may require attention if the tree is retained, and '3' indicates significant visible problems or defects and tree removal is recommended.

**Visible defects** Obvious structural defects or diseases visible at time of inspection, which includes:

Asymmetric canopy– the tree has an asymmetric canopy from space and light competition from adjacent trees.

Branch dieback - mature branches in canopy are dying/dead.

Crack – separation of wood fibers and predisposed to failure.

Dead – tree is dead.

Deadwood – large and/or multiple dead branches throughout canopy.

Decay – process of wood degradation by microorganisms resulting in weak and defective structure.

Diseased – foliage and trunk/stems are diseased.

Dogleg in trunk – trunk with a bow or defective bend (90°) in trunk often half way of further up the trunk.

Double leader – the tree has multiple stem attachments, which may require maintenance or monitoring over time.

Included bark - bark inclusion at attachment of multiple leaders and is preventing a wood-to-wood attachment

Insect Injury – active insect injury affecting tree health.

Ivy - dense ivy prevents a thorough inspection, and other defects may be present.

Kretzschmaria fungus indicated internal wood decay.

Multiple leaders - the tree has multiple stem attachments, which may lead to tree failure and require maintenance or monitoring over time.

Previous failure – tree trunk previously broken and defective.

Sweep in trunk – characterized by a leaning lower trunk and a more upright top.

Thinning Canopy – low foliage density may indicate stress, or early infection/declining health.

Robert Londo, Orcas Moon, LLC

RE: Arborist Report at Forbes Creek, TPN 3890100050 & 3890100055.

November 20, 2017

Page 4 of 21

Stumpsprout- tree previously cut at grade with multiple stems and potentially weak attachments.

Suppressed – tree crowded by larger adjacent trees; with defective structure and/or low vigor. Retain tree only as a grove tree, not stand-alone.

Sweep – tree leans away from adjacent trees. Characterized by a leaning lower trunk and a top that is more upright.

Topped – the tree is previously topped and has poor structure and/or stem decay.

Tree leans – trunk has significant lean from vertical.

Tree suppressed -tree is suppressed by adjacent tree canopies.

Trunk decay - wood decay is visible in the trunk.

Wound/decay base of trunk - open wound with visible decay in trunk.

**Viable Tree** a determination by the arborist whether the tree is viable for retention.

Non-viable trees are indicated.

#### REQUIRED TREE DENSITY & AVAILABLE TREE DENSITY CREDIT

Required tree density is calculated by multiplying the acreage of the lot by 30, which equals 194. ( $6.44 \times 30 = 193.2$  or 194 rounded) The required minimum tree density credit for this site = 194. The total tree density credits for retained trees is 222.5. (See attachment 3). The calculated (retained) tree density is above the required minimum and no supplemental trees are needed.

#### LIMITS OF DISTURBANCE

Limits of Disturbance (LOD) are calculated for all the retained *significant* and *impacted* trees. They are listed below as radii in feet from the trunk. They are determined using rootplate<sup>1</sup> and trunk diameter,<sup>2,3</sup> and ISA Best Management Practices.<sup>4</sup> These are the minimum distances from the trees for any soil disturbance, and represent the area to be protected during construction.

These LOD also assume disturbance on multiple sides of a tree, and they are malleable, particularly where disturbance is proposed on only a single side of the tree, and may be adjusted during the construction process.

<sup>1</sup> Coder, Kim D. 2005. *Tree Biomechanics Series*. University of Georgia School of Forest Resources.

<sup>2</sup> Smiley, E. Thomas, Ph. D. *Assessing the Failure Potential of Tree Roots, Shade Tree Technical Report*. Bartlett Tree Research Laboratories.

<sup>3</sup> Fite, Kelby and E. Thomas Smiley. 2009. *Managing Trees During construction; Part Two*. Arborist News. ISA.

<sup>4</sup> Companion publication to the ANSI A300 Series, Part 5: *Managing Trees During Construction*. 2008. ISA.

Robert Londo, Orcas Moon, LLC

RE: Arborist Report at Forbes Creek, TPN 3890100050 & 3890100055.

November 20, 2017

Page 5 of 21

The following table establishes the limits of disturbance of each tree.

Proposed Action	TREE NO.	DBH	Species	DL	LOD
SAVE	20235	12"	Red alder	16'	6'
SAVE	20240	8"	Red alder	0'	6'
SAVE	20241	10"	Red alder	14'	6'
SAVE	20243	8"	Red alder	12'	5.5'
SAVE	20244	6"	Red alder	0'	6'
SAVE	20247	10"	Red alder	14'	6'
SAVE	20249	6"	Red alder	6'	5'
SAVE	20251	8"	Red alder	14'	5.5'
SAVE	20254	6"	Red alder	10'	5'
SAVE	20256	8"	Red alder	10'	5.5'
SAVE	20259	8"	Red alder	12'	5.5'
SAVE	20260	10"	Red alder	16'	6'
SAVE	20261	6"	Red alder	12'	5'
SAVE	20262	6"	Red alder	8'	5'
SAVE	20263	10"	Red alder	16'	6'
SAVE	20264	8"	Red alder	12'	5.5'
SAVE	20265	8"	Red alder	14'	5.5'
SAVE	20266	6"	Red alder	6'	5'
SAVE	20267	6"	Red alder	8'	5'
SAVE	20268	8"	Red alder	14'	5.5'
SAVE	20269	6"	Red alder	8'	5'
SAVE	20270	8"	Red alder	10'	5.5'
SAVE	20271	10"	Red alder	14'	6'
SAVE	20272	8"	Western red-cedar	10'	5.5'
SAVE	20273	8"	Red alder	14'	5.5'
SAVE	20274	8"	Red alder	12'	5.5'
SAVE	20275	8"	Red alder	12'	5.5'
SAVE	20276	8"	Red alder	14'	5.5'
SAVE	20277	8"	Red alder	14'	5.5'
SAVE	20279	8"	Red alder	10'	5.5'
IMPACTED	20280	6"	Red alder	10'	6'
IMPACTED	20281	8"	Red alder	12'	6'
SAVE	20286	6"	Red alder	8'	5'
SAVE	20288	6"	Red alder	8'	5'



Robert Londo, Orcas Moon, LLC

RE: Arborist Report at Forbes Creek, TPN 3890100050 &amp; 3890100055.

November 20, 2017

Page 6 of 21

Proposed Action	TREE NO.	DBH	Species	DL	LOD
SAVE	20349	22,20"	Bigleaf maple	30'	13'
SAVE	20361	24",22",18",10"	Bigleaf maple	30'	17'
SAVE	20363	24,24"	Bigleaf maple	25'	15'
SAVE	20364	24"	Bigleaf maple	30	12'
SAVE	20366	38,40"	Black cottonwood	25'	18'
SAVE	20412	12"	Red alder	16'	6'
SAVE	20413	8"	Red alder	14'	5.5'
SAVE	20414	8"	Red alder	14'	5.5'
SAVE	20415	10"	Red alder	14'	6'
SAVE	20416	6,8"	Red alder	14'	6'
SAVE	20417	7"	Red alder	4'	5'
SAVE	20418	10"	Red alder	14'	6'
SAVE	20419	8"	Red alder	10'	5.5'
SAVE	20420	8"	Red alder	10'	5.5'
SAVE	20421	8"	Red alder	10'	5.5'
SAVE	20427	16"	Red alder	14'	8'
SAVE	20429	18"	Bigleaf maple	20'	8'
SAVE	20460	6,24,30,34"	Bigleaf maple	25'	20'
SAVE	20470	16"	Bigleaf maple	14'	8'
IMPACTED	20495	16"	Bigleaf maple	16'	8'
SAVE	20562	42"	Douglas-fir	20'	19'
IMPACTED	20674	32,22,10"	Bigleaf maple	30'	15'
IMPACTED	20675	24,18"	Bigleaf maple	25'	11'
SAVE	20688	14"	Douglas-fir	16'	7'
IMPACTED	20702	16"	Bigleaf maple	14'	8'
SAVE	20709	24"	Bigleaf maple	16'	12'
SAVE	20730	10"	Western red-cedar	12'	6'
IMPACTED	20731	20"	Western red-cedar	16'	8'
SAVE	20732	28,30,30,24"	Bigleaf maple	35'	21'
SAVE	20733	8,12"	Bigleaf maple	16'	8'
SAVE	20735	22"	Bigleaf maple	18'	11'
SAVE	20793	6"	Pacific dogwood	8'	5'
SAVE	20807	14"	Western red-cedar	10'	7'
SAVE	20989	14,16"	Bigleaf maple	14'	11'



Robert Londo, Orcas Moon, LLC  
RE: Arborist Report at Forbes Creek, TPN 3890100050 & 3890100055.  
November 20, 2017  
Page 7 of 21

No work is proposed within the critical root zone of a retained tree.

#### LOCATION AND TYPE OF PROTECTION MEASURES FOR TREES.

Minimum six (6) foot temporary chain-link fence shall be installed at the driplines of all retained trees, or at the limits of disturbance when construction or access is required or proposed within the dripline. Fence shall completely encircle the retained trees and shall be installed prior to site clearing. Install fence posts using pier block only. A City planner must approve any modifications to the fencing material and location.

No stockpiling of materials, vehicular or pedestrian traffic, material storage or use of equipment or machinery shall be allowed within the protective fencing. Fencing shall not be moved or removed unless approved by a City planner. Any work, activity or soil disturbance within the protection fencing, or critical root zone, shall be reviewed, approved and monitored by the project arborist.

Instructions and specifications for pruning roots or branches shall be addressed individually for specific trees based on the proposed encroachment.

Fencing signage as detailed (see attached) must be posted every fifteen (15) feet along the fencing.

#### Attachments

1. Assumptions and Limiting Conditions
2. Certification of Performance
3. Regulated Tree Inventory
4. Tree Retention Plan
5. Tree Protection Detail

Robert Londo, Orcas Moon, LLC  
RE: Arborist Report at Forbes Creek, TPN 3890100050 & 3890100055.  
November 20, 2017  
Page 8 of 21

#### Attachment No. 1 - Assumptions & Limiting Conditions

1. A field examination of the site was made 7/19/2016. My observations and conclusions are as of that date.
2. Care has been taken to obtain all information from reliable sources. All data has been verified insofar as possible; however, the consultant/arborist can neither guarantee nor be responsible for the accuracy of information provided by others.
3. I am not a qualified land surveyor. Reasonable care was used to match the trees indicated on the sheets with those growing in the field.
4. Construction activities can significantly affect the condition of retained trees. All retained trees should be inspected after construction is completed, and then inspected regularly as part of routine maintenance.
5. Unless stated other wise: 1) information contained in this report covers only those trees that were examined and reflects the condition of those trees at the time of inspection; and 2) the inspection is limited to visual examination of the subject trees without dissection, excavation, probing, or coring. There is no warranty or guarantee, expressed or implied that problems or deficiencies of the subject tree may not arise in the future.
6. All trees possess the risk of failure. Trees can fail at any time, with or without obvious defects, and with or without applied stress. A complete evaluation of the potential for this (a) tree to fail requires excavation and examination of the base of the subject tree. Permission of the current property owner must be obtained before this work can be undertaken and the hazard evaluation completed.
7. The consultant/appraiser shall not be required to give testimony or to attend court by reason of this report unless subsequent contractual arrangements are made.

Robert Londo, Orcas Moon, LLC  
RE: Arborist Report at Forbes Creek, TPN 3890100050 & 3890100055.  
November 20, 2017  
Page 9 of 21

Attachment No. 2 – Certification of Performance


---

I, Favero Greenforest, certify that:

- I have personally inspected the trees and the property referred to in this report and have stated my findings accurately.
- I have no current or prospective interest in the vegetation or the property that is the subject of this report and have no personal interest or bias with respect to the parties involved.
- The analysis, opinion, and conclusions stated herein are my own and are based on current scientific procedures and facts.
- My analysis, opinion, and conclusions were developed and this report has been prepared according to commonly accepted arboricultural practices.
- No one provided significant professional assistance to me, except as indicated within the report.
- My compensation is not contingent upon the reporting of a predetermined conclusion that favors the cause of the client of any other party nor upon the results of the assessment, the attainment of stipulated results, or the occurrence of any subsequent events.

I further certify that I am a member in good standing of International Society of Arboriculture (ISA), and the ISA PNW Chapter, I am an ISA Certified Arborist (#PN-0143A) and am Tree Risk Assessment Qualified, and am a Registered Consulting Arborist® (#379) with American Society of Consulting Arborists. I have worked as an independent consulting arborist since 1989.

Signed:



GREENFOREST, Inc.

By Favero Greenforest, M. S.

Date: November 20, 2017



Robert Londo, Orcas Moon, LLC

RE: Arborist Report at Forbes Creek, TPN 3890100050 &amp; 3890100055.

November 20, 2017

Page 10 of 21

## Attachment No. 3 – Regulated Tree Inventory

Parcel	Proposed Action	Density Credits	Retained TDC	TREE NO.	DBH	Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
B	SAVE	2	2	20235	12	Red alder	16	1	2	Decline	
A	OFFSITE	0	0	20236	36	Weeping willow	35	2	2	Diseased, ivy	
A	NON-VIABLE	0	0	20237	12	Red alder	18	1	3	Upper trunk decay	NO
A	NON-VIABLE	0	0	20238	10	Red alder	12	1	3	Trunk failure	NO
A	OFFSITE	0	0	20239	10	Red alder	14	1	2	Asymmetric canopy	
B	SAVE	0	0	20240	8	Red alder	0	3	3	Covered in vines	NO
B	SAVE	1	1	20241	10	Red alder	14	1	2	Asymmetric, vines	
B	SAVE	1	1	20243	8	Red alder	12	1	2	Asymmetric	
B	SAVE	0	0	20244	6	Red alder	0	3	3	Covered in vines	NO
B	NON-VIABLE	0	0	20246	8	Red alder	6	1	3	Adjacent tree fell into it	NO
B	SAVE	1	1	20247	10	Red alder	14	1	2	Asymmetric	
B	SAVE	1	1	20249	6	Red alder	6	1	2	Suppressed	
A	NON-VIABLE	0	0	20250	16	Weeping willow	12	1	3	Previous trunk failure	NO
B	SAVE	1	1	20251	8	Red alder	14	1	2	Asymmetric	
B	SAVE	1	1	20254	6	Red alder	10	1	2	Suppressed	
B	SAVE	1	1	20256	8	Red alder	10	1	2	Asymmetric	
B	NON-VIABLE	0	0	20257	8	Red alder	14	1	3	Asymmetric, trunk injury	NO
B	NON-VIABLE	0	0	20258	8	Red alder	14	1	2	Lean, asymmetric	
B	SAVE	1	1	20259	8	Red alder	12	1	2	Asymmetric, lean	
B	SAVE	1	1	20260	10	Red alder	16	1	2	Asymmetric	
B	SAVE	1	1	20261	6	Red alder	12	1	2	Suppressed	
B	SAVE	1	1	20262	6	Red alder	8	1	2	Asymmetric	

Robert Londo, Orcas Moon, LLC

RE: Arborist Report at Forbes Creek, TPN 3890100050 &amp; 3890100055.

November 20, 2017

Page 11 of 21

Parcel	Proposed Action	Density Credits	Retained TDC	TREE NO.	DBH	Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
B	SAVE	1	1	20263	10	Red alder	16	1	2	Asymmetric	
B	SAVE	1	1	20264	8	Red alder	12	1	1		
B	SAVE	1	1	20265	8	Red alder	14	1	2	Asymmetric	
B	SAVE	1	1	20266	6	Red alder	6	1	2	Suppressed	
B	SAVE	1	1	20267	6	Red alder	8	1	2	Asymmetric	
B	SAVE	1	1	20268	8	Red alder	14	1	2	Lean	
B	SAVE	1	1	20269	6	Red alder	8	1	2	Suppressed	
B	SAVE	1	1	20270	8	Red alder	10	1	1		
B	SAVE	1	1	20271	10	Red alder	14	1	1		
B	SAVE	1	1.5	20272	8	Western red-cedar	10	1	1		
B	SAVE	1	1	20273	8	Red alder	14	1	2	Asymmetric	
B	SAVE	1	1	20274	8	Red alder	12	1	2	Asymmetric	
B	SAVE	1	1	20275	8	Red alder	12	1	2	Lean	
B	SAVE	1	1	20276	8	Red alder	14	1	2	Suppressed	
B	SAVE	1	1	20277	8	Red alder	14	1	2	Sweep	
A	NON-VIABLE	0	0	20278	28	Red alder	12	2	3	Decline, decay	NO
B	SAVE	1	1	20279	8	Red alder	10	1	1		
B	IMPACTED	0	0	20280	6	Red alder	10	1	2	Lean	
B	IMPACTED	0	0	20281	8	Red alder	12	1	1		
B	REMOVE	0	0	20283	12	Red alder	12	1	2	Asymmetric	
B	SAVE	1	1	20286	6	Red alder	8	1	1		
B	SAVE	1	1	20288	6	Red alder	8	2	1	Stem canker	

Robert Londo, Orcas Moon, LLC

RE: Arborist Report at Forbes Creek, TPN 3890100050 &amp; 3890100055.

November 20, 2017

Page 12 of 21

Parcel	Proposed Action	Density Credits	Retained TDC	TREE NO.	DBH	Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
B	REMOVE	0	0	20292	18	Bitter cherry	16	1	2	Asymmetric	
B	NON-VIABLE	0	0	20293	6	Red alder	8	1	3	Root failure	NO
B	NON-VIABLE	0	0	20294	12	Red alder	10	3	3	Decline, vine, dying-nearly dead	NO
B	REMOVE	0	0	20296	22,40	Bigleaf maple	35	1	2	Soil heave	
A	NON-VIABLE	0	0	20297	18	Douglas-fir	16	1	1		
A	OFFSITE	0	0	20307	6	Douglas-fir	8	1	2	Suppressed	
A	NON-VIABLE	0	0	20309	38	Bigleaf maple	30	1	3	Decay, Kretzschmaria	NO
A	OFFSITE	0	0	20319	6	Douglas-fir	6	1	2	Suppressed	
A	OFFSITE	0	0	20321	6	Red alder	8	1	1		
A	OFFSITE	0	0	20324	12	Douglas-fir	14	1	1		
B	SAVE	11	11	20349	22,20	Bigleaf maple	30	1	2	Double leader	
A	NON-VIABLE	0	0	20350	10",18", 18",16	Bigleaf maple	20	2	3	Decline, stump sprout, Kretzschmaria	NO
A	OFFSITE	0	0	20351	20	Bigleaf maple	20	1	1		
A	OFFSITE	0	0	20352	14,12,22	Bigleaf maple	18	1	2	Multiple leaders	
A	OFFSITE	0	0	20353	14",16", 18",18	Bigleaf maple	25	2	2	Decay, multiple leaders, chain embedded in trunk	
B	NON-VIABLE	0	0	20354	18	Bigleaf maple	16	2	3	Decline, trunk decay, Kretzschmaria	NO
B	NON-VIABLE	0	0	20355	10,14,14"	Bigleaf maple	16	2	3	Decline, trunk decay, Kretzschmaria	NO
B	NON-VIABLE	0	0	20356	24	Bigleaf maple	18	2	3	Decline, Kretzschmaria	NO
B	REMOVE	0	0	20357	14	Douglas-fir	12	1	2	Ivy	

Robert Londo, Orcas Moon, LLC

RE: Arborist Report at Forbes Creek, TPN 3890100050 &amp; 3890100055.

November 20, 2017

Page 13 of 21

Parcel	Proposed Action	Density Credits	Retained TDC	TREE NO.	DBH	Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
B	NON-VIABLE	0	0	20358	18	Bitter cherry	12	2	3	Decline, stem failure	NO
B	REMOVE	0	0	20359	6	Douglas-fir	6	1	2	Suppressed	
A	REMOVE	0	0	20360	22	Red alder	16	2	2	Decline, double leader	
B	SAVE	15	15	20361	24",22", 18",10	Bigleaf maple	30	1	2	Multiple leaders	
A	REMOVE	0	0	20362	10,14,14"	Western red-cedar	12	1	1		
B	SAVE	13	13	20363	24,24	Bigleaf maple	25	1	2	Double leader	
B	SAVE	8	8	20364	24	Bigleaf maple	30	1	1		
B	SAVE	21	21	20366	38,40	Black cottonwood	25	1	2	Double leader	
B	NON-VIABLE	0	0	20367	14	Red alder	10	1	3	Lean, ivy	NO
B	REMOVE	0	0	20368	10	Red alder	12	2	2	Decline, nearly dead	
B	SAVE	2	2	20412	12	Red alder	16	1	1		
B	SAVE	1	1	20413	8	Red alder	14	1	2	Asymmetric	
B	SAVE	1	1	20414	8	Red alder	14	1	2	asymmetric	
B	SAVE	1	1	20415	10	Red alder	14	1	1		
B	SAVE	1	1	20416	6,8	Red alder	14	1	2	Asymmetric, double leader, included bark	
B	SAVE	1	1	20417	7	Red alder	4	1	1		
B	SAVE	1	1	20418	10	Red alder	14	1	1		
B	SAVE	1	1	20419	8	Red alder	10	1	2	Asymmetric	
B	SAVE	1	1	20420	8	Red alder	10	1	2	Asymmetric	
B	SAVE	1	1	20421	8	Red alder	10	1	2	Asymmetric	
B	SAVE	0	0	20427	16	Red alder	14	2	3	Decline, deadwood	NO



Robert Londo, Orcas Moon, LLC

RE: Arborist Report at Forbes Creek, TPN 3890100050 &amp; 3890100055.

November 20, 2017

Page 14 of 21

Parcel	Proposed Action	Density Credits	Retained TDC	TREE NO.	DBH	Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
B	NON-VIABLE	0	0	20428	12	Bigleaf maple	16	1	2	Asymmetric	
B	SAVE	5	5	20429	18	Bigleaf maple	20	2	1	Stunted upper foliage	
B	REMOVE	0	0	20447	18,20,24,28	Bigleaf maple	25	1	2	Multiple leaders	
B	REMOVE	0	0	20448	36,38	Bigleaf maple	20	1	2	Double leader	
B	REMOVE	0	0	20449	16	Bigleaf maple	18	1	1		
B	REMOVE	0	0	20450	52	Black cottonwood	25	1	2	Asymmetric, sweep	
B	REMOVE	0	0	20451	65	Black cottonwood	25	1	2	Asymmetric, sweep	
B	REMOVE	0	0	20452	44	Black cottonwood	25	1	2	Asymmetric, sweep	
B	NON-VIABLE	0	0	20453	10,18,20,20,26,30	Bigleaf maple	30	1	3	Previous failure, multiple leaders, stump sprout	NO
B	REMOVE	0	0	20454	30	Black cottonwood	25	1	2	Asymmetric, sweet	
B	REMOVE	0	0	20456	26	Black cottonwood	25	1	2	Asymmetric, sweet	
B	SAVE	21	21	20460	6,24,30,34	Bigleaf maple	25	1	2	Multiple leaders	
B	SAVE	4	4	20470	16	Bigleaf maple	14	1	2	Trunk wound, deadwood	
B	IMPACTED	0	0	20495	16	Bigleaf maple	16	1	1		
B	REMOVE	0	0	20528	16	Bigleaf maple	18	1	2	Asymmetric	
B	REMOVE	0	0	20530	8	Douglas-fir	6	1	2	Suppressed	
B	REMOVE	0	0	20532	18	Bigleaf maple	18	1	2	Deadwood, asymmetric	
B	REMOVE	0	0	20536	50	Black cottonwood	30	1	1		
B	REMOVE	0	0	20540	30	Bigleaf maple	20	1	2	Asymmetric	
B	REMOVE	0	0	20543	20	Western red-cedar	14	1	1		
B	REMOVE	0	0	20544	54	Black cottonwood	20	1	2	Sweep in trunk	
B	NON-VIABLE	0	0	20545	18,16,16	Bigleaf maple	20	2	3	Stunted, trunk failure,	NO

Robert Londo, Orcas Moon, LLC

RE: Arborist Report at Forbes Creek, TPN 3890100050 &amp; 3890100055.

November 20, 2017

Page 15 of 21

Parcel	Proposed Action	Density Credits	Retained TDC	TREE NO.	DBH	Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
										stumpsprout	
B	REMOVE	0	0	20546	6	Western red-cedar	8	1	2	Suppressed	
B	REMOVE	0	0	20547	28	Bigleaf maple	25	1	2	Branch failure, asymmetric	
B	REMOVE	0	0	20548	14	Western red-cedar	12	1	2	Suppressed	
B	REMOVE	0	0	20549	12	Western red-cedar	14	1	2	Suppressed	
B	REMOVE	0	0	20550	24	Bigleaf maple	18	1	2	Asymmetric	
B	REMOVE	0	0	20551	18	Bigleaf maple	16	1	2	Seam in trunk	
B	SAVE	17	25.5	20562	42	Douglas-fir	20	1	1		
B	REMOVE	0	0	20666	40	Bigleaf maple	25	1	2	Spiral cracks in trunk	
B	REMOVE	0	0	20667	16	Western hemlock	16	1	1		
B	NON-VIABLE	0	0	20668	8	Bigleaf maple	14	1	3	Asymmetric, suppressed	NO
B	IMPACTED	0	0	20674	32,22,10	Bigleaf maple	30	1	2	Multiple leaders	
B	IMPACTED	0	0	20675	24,18	Bigleaf maple	25	2	2	Stunted foliage, stump sprout	
B	REMOVE	0	0	20678	2-20",18", 2-12",10", 26",34",16	Bigleaf maple	25	2	2	Stunted foliage, multiple leader, deadwood	
B	REMOVE	0	0	20679	10	Douglas-fir	12	1	2	Suppressed	
B	REMOVE	0	0	20682	24	Douglas-fir	18	1	1		
B	REMOVE	0	0	20683	22	Bigleaf maple	18	1	2	Asymmetric	
B	REMOVE	0	0	20684	24	Western red-cedar	18	1	2	Double leader	
B	SAVE	3	4.5	20688	14	Douglas-fir	16	1	2	Dogleg, double leader	
B	REMOVE	0	0	20689	26	Western red-cedar	16	1	1		



Robert Londo, Orcas Moon, LLC

RE: Arborist Report at Forbes Creek, TPN 3890100050 &amp; 3890100055.

November 20, 2017

Page 16 of 21

Parcel	Proposed Action	Density Credits	Retained TDC	TREE NO.	DBH	Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
B	REMOVE	0	0	20690	18	Western red-cedar	16	1	1		
B	REMOVE	0	0	20691	8	Western red-cedar	8	1	2	Asymmetric	
B	NON-VIABLE	0	0	20693	10	Red alder	14	1	3	Lean	NO
B	REMOVE	0	0	20694	18	Western red-cedar	12	1	2	Sweep in trunk	
B	REMOVE	0	0	20695	16	Western hemlock	14	1	1		
B	REMOVE	0	0	20696	14	Western red-cedar	12	1	1		
B	NON-VIABLE	0	0	20697	16	Red alder	12	1	3	Top of tree is dead	NO
B	REMOVE	0	0	20699	34	Bigleaf maple	25	1	2	Asymmetric	
B	REMOVE	0	0	20700	20	Western red-cedar	14	1	1		
B	IMPACTED	0	0	20702	16	Bigleaf maple	14	1	1		
B	REMOVE	0	0	20703	8	Western hemlock	10	1	2	Suppressed	
B	REMOVE	0	0	20704	18	Bigleaf maple	18	1	2	Deadwood	
B	SAVE	8	8	20709	24	Bigleaf maple	16	1	1		
B	NON-VIABLE	0	0	20714	14	Bigleaf maple	16	1	3	Asymmetric, trunk decay	NO
B	REMOVE	0	0	20715	16	Bigleaf maple	16	1	2	Asymmetric	
B	REMOVE	0	0	20716	28	Bigleaf maple	20	1	1		
B	REMOVE	0	0	20717	12	Western hemlock	14	1	2	Suppressed	
B	REMOVE	0	0	20718	20	Bigleaf maple	18	1	1		
B	REMOVE	0	0	20719	22	Bigleaf maple	18	1	2	Asymmetric	
B	REMOVE	0	0	20720	6	Douglas-fir	8	1	2	Suppressed	
B	NON-VIABLE	0	0	20721	20	Bigleaf maple	18	1	3	Trunk decay	NO
B	REMOVE	0	0	20722	24	Bigleaf maple	20	1	2	Asymmetric	



Robert Londo, Orcas Moon, LLC

RE: Arborist Report at Forbes Creek, TPN 3890100050 &amp; 3890100055.

November 20, 2017

Page 17 of 21

Parcel	Proposed Action	Density Credits	Retained TDC	TREE NO.	DBH	Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
B	REMOVE	0	0	20724	18,24	Bigleaf maple	20	1	3	Stumpsprout	NO
B	NON-VIABLE	0	0	20726	16	Bigleaf maple	18	1	3	Dog leg, stumpsprout	NO
B	NON-VIABLE	0	0	20727	12	Bigleaf maple	16	1	3	Asymmetric, lean	NO
B	SAVE	1	1.5	20730	10	Western red-cedar	12	1	1		
B	IMPACTED	0	0	20731	20	Western red-cedar	16	1	1		
B	SAVE	21	21	20732	28,30,30,24	Bigleaf maple	35	1	2	Deadwood, failure, stumpsprout	
B	SAVE	3	3	20733	8,12	Bigleaf maple	16	1	2	Asymmetric, stumpsprout	
B	NON-VIABLE	0	0	20734	32,26	Bigleaf maple	25	1	3	Trunk decay, stumpsprout, Kretschmaria	NO
B	SAVE	7	7	20735	22	Bigleaf maple	18	1	2	Deadwood, asymmetric	
B	REMOVE	0	0	20736	16	Bigleaf maple	18	1	2	Asymmetric, stumpsprout	
B	NON-VIABLE	0	0	20737	16	Bigleaf maple	16	1	3	Leaning in adjacent tree	NO
B	REMOVE	0	0	20738	6,14	Bigleaf maple	18	1	2	Stump sprout	
B	NON-VIABLE	0	0	20739	20	Bigleaf maple	20	1	3	Stump sprout	NO
B	NON-VIABLE	0	0	20740	18	Bigleaf maple	16	1	3	Dog leg, branch failure, stumpsprout	NO
B	REMOVE	0	0	20741	18	Western red-cedar	16	1	1		
B	REMOVE	0	0	20742	22	Western red-cedar	16	1	1		
B	REMOVE	0	0	20743	16	Western red-cedar	14	1	2	Growing against maple	
B	REMOVE	0	0	20744	16	Bigleaf maple	16	1	2	Previous branch failure, sweep in trunk	
B	REMOVE	0	0	20748	14	Bigleaf maple	16	1	2	Asymmetric	

Robert Londo, Orcas Moon, LLC

RE: Arborist Report at Forbes Creek, TPN 3890100050 &amp; 3890100055.

November 20, 2017

Page 18 of 21

Parcel	Proposed Action	Density Credits	Retained TDC	TREE NO.	DBH	Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
B	NON-VIABLE	0	0	20749	6	Bigleaf maple	12	1	3	Dog leg, trunk injury, stumpsprout	NO
B	NON-VIABLE	0	0	20751	6,6,8,18,24	Bigleaf maple	25	2	3	Decline, decay, stumpsprout	NO
B	REMOVE	0	0	20780	16	Bigleaf maple	18	1	2	Dog leg in trunk	
B	SAVE	1	1	20793	6	Pacific dogwood	8	1	2	deadwood	
B	SAVE	3	4.5	20807	14	Western red-cedar	10	1	2	Sweep in trunk	
B	NON-VIABLE	0	0	20862	12	Red alder	8	2	3	Decline	NO
B	REMOVE	0	0	20864	16	Red alder	14	1	1		
B	NON-VIABLE	0	0	20870	8,12,18	Bigleaf maple	18	1	3	Asymmetric, stumpsprout	NO
B	REMOVE	0	0	20934	6	Red alder	8	1	1		
B	NON-VIABLE	0	0	20978	12,14	Red alder	12	2	3	Top failure	NO
B	NON-VIABLE	0	0	20979	10	Red alder	8	2	3	Top of tree is dead	NO
B	REMOVE	0	0	20982	22,26	Bigleaf maple	18	1	2	Trunk decay	
B	SAVE	6	6	20989	14,16	Bigleaf maple	14	1	2	dogleg, asymmetric	
B	NON-VIABLE	0	0	20990	18	Scouler's willow	14	1	3	leaning trunk	NO
A	NON-VIABLE	0	0	21020	10	Red alder	14	1	3	Trunk wound/decay	NO
A	OFFSITE	0	0	21021	18	Douglas-fir	16	1	2	Topped for power lines	
B	REMOVE	0	0	21022	16	Douglas-fir	16	1	2	Topped for power lines	
A	NON-VIABLE	0	0	21024	7	Red alder	8	2	3	Decline, decay	NO
A	NON-VIABLE	0	0	21025	7	Red alder	8	2	3	Decline, decay	NO
A	OFFSITE	0	0	21026	20	Western red-cedar	14	1	1		
A	OFFSITE	0	0	21027	7	Red alder	10	2	2	Decline, decay	



Robert Londo, Orcas Moon, LLC

RE: Arborist Report at Forbes Creek, TPN 3890100050 &amp; 3890100055.

November 20, 2017



Page 19 of 21

Parcel	Proposed Action	Density Credits	Retained TDC	TREE NO.	DBH	Species	Dripline	Health	Structure	Visible Defects	Viable Tree?
A	OFFSITE	0	0	21028	10	Red alder	10	1	1		
A	OFFSITE	0	0	21029	6",12",14",16", 10",18",8"	Western red-cedar	16	1	2	Stump sprout	
B	NON-VIABLE	0	0	22119	14	Western hemlock	10	1	3	Branch decline, spiral cracks in trunk	NO
B	REMOVE	0	0	22120	18	Western red-cedar	14	1	2	Asymmetric	
B	REMOVE	0	0	22121	18	Western red-cedar	14	1	2	Asymmetric	
B	REMOVE	0	0	A	8	Douglas-fir	6	1	1		
B	REMOVE	0	0	B	8	Western red-cedar	6	1	2	Sweep	
B	NON-VIABLE	0	0	C	24	Bigleaf maple	16	1	3	Trunk decay	NO
B	REMOVE	0	0	D	48	Black cottonwood	25	1	1		
B	NON-VIABLE	0	0	E	16	Bigleaf maple	18	1	3	Asymmetric, stumpsprout	NO
<b>Tree Credits</b>		210	222.5	Retained TDC of 222.5 includes 1.5x for retained native conifers. DBH – trunk diameter in inches 4.5' from grade. Dripline as radius in feet from the trunk.							



Robert Londo, Orcas Moon, LLC  
 RE: Tree Inventory at Forbes Creek, TPN 3890100050 & 3890100055.  
 November 20, 2017  
 Page 20 of 21  
 Attachment No. 4 - Preliminary Tree Retention Plan

SW 1/4, SEC 32, TWP 26N, R6E, SE W.M.



**TREE PROTECTION MEASURES**

- TREE PROTECTION FENCES WILL NEED TO BE PLACED AROUND EACH TREE OR GROUP OF TREES TO BE RETAINED.
  - TREE PROTECTION FENCES ARE TO BE PLACED ACCORDING TO CITY STANDARD PLAN NO. 06-2-49 AND AS NOTED IN THE TREE INVENTORY/CONDITIONS SPREADSHEET, COLUMN 6 - LIMITS OF DISTURBANCE (SEE ARBORIST REPORT DATED 6/14/17).
  - TREE PROTECTION FENCES MUST BE INSPECTED PRIOR TO THE BEGINNING OF ANY CONSTRUCTION WORK/ACTIVITIES.
  - NOTHING MUST BE PARKED OR STORED WITHIN THE TREE PROTECTION FENCES—NO EQUIPMENT, VEHICLES, SOIL, DEBRIS, OR CONSTRUCTION SUPPLIES OF ANY SORTS.
- CEMENT TRUCKS MUST NOT BE ALLOWED TO DEPOSIT WASTE OR WASH OUT MATERIALS FROM THEIR TRUCKS WITHIN THE TREE PROTECTION FENCES.
- TREE PROTECTION FENCES NEED TO BE CLEARLY MARKED WITH THE FOLLOWING OR SIMILAR TEXT IN FOUR INCH OR LARGER LETTERS:
 

TREE PROTECTION AREA, ENTRANCE PROHIBITED  
 TO REPORT VIOLATIONS CONTACT  
 CITY CODE ENFORCEMENT AT  
 425-587-3225
- THE AREA WITHIN THE TREE PROTECTION FENCING MUST BE COVERED WITH WOOD CHIPS, HOG FUEL, OR SIMILAR MATERIALS TO A DEPTH OF 4 TO 18 INCHES. THE MATERIALS SHOULD BE PLACED PRIOR TO BEGINNING CONSTRUCTION AND REMAIN UNTIL THE TREE PROTECTION FENCING IS TAKEN DOWN.
- WHEN EXCAVATION OCCURS NEAR TREES THAT ARE SCHEDULED FOR RETENTION, THE FOLLOWING PROCEDURE MUST BE FOLLOWED TO PROTECT THE LONG TERM SURVIVABILITY OF THE TREE:
  - AN INTERNATIONAL SOCIETY OF ARBORICULTURE (ISA) CERTIFIED ARBORIST MUST BE WORKING WITH ALL EQUIPMENT OPERATOR.
  - THE CERTIFIED ARBORIST SHOULD BE OUTFITTED WITH A SHOVEL, HAND PRUNERS, A PAIR OF LOPPERS, A HANDSAW, AND A POWER SAW (A "SAWSALL" IS RECOMMENDED).
  - COMBING IS THE GRADUAL EXCAVATION OF THE GROUND COVER PLANTS AND SOIL IN DEPTHS THAT ONLY EXTEND AS DEEP AS THE TINES OF THE HOE.
  - WHEN ANY ROOTS OF ONE INCH DIAMETER OR GREATER OF THE TREE TO BE RETAINED, IS STRUCK BY THE EQUIPMENT, THE CERTIFIED ARBORIST SHOULD STOP THE EQUIPMENT OPERATOR.
  - THE CERTIFIED ARBORIST SHOULD THEN EXCAVATE AROUND THE TREE ROOT BY HAND/SHOVEL AND CLEANLY CUT THE TREE ROOT.
  - THE CERTIFIED ARBORIST SHOULD THEN INSTRUCT THE EQUIPMENT OPERATOR TO CONTINUE.
- PUTTING UTILITIES UNDER THE ROOT ZONE:
  - BORING UNDER THE ROOT SYSTEMS OF TREES (AND OTHER VEGETATION) SHALL BE DONE UNDER THE SUPERVISION OF AN ISA CERTIFIED ARBORIST. THIS IS TO BE ACCOMPLISHED BY EXCAVATING A LIMITED TRENCH ON EACH SIDE OF THE CRITICAL ROOT ZONE OF THE TREE AND THEN HAND DIGGING OR PUSHING THE PIPE THROUGH THE SOIL UNDER THE TREE. THE CLOSEST PIT WALLS SHALL BE A MINIMUM OF 7 FEET FROM THE CENTER OF THE TREE AND SHALL BE SUFFICIENT DEPTH TO LAY THE PIPE AT THE GRADE AS SHOWN ON THE PLAN AND PROFILE.
  - TUNNELING UNDER THE ROOTS OF TREES SHALL BE DONE UNDER THE SUPERVISION OF AN ISA CERTIFIED ARBORIST IN AN OPEN TRENCH BY CAREFULLY EXCAVATING AND HAND DIGGING AROUND AREAS WHERE LARGER ROOTS ARE EXPOSED. NO ROOTS 1 INCH IN DIAMETER OR LARGER SHALL BE CUT. THE CONTRACTOR SHALL VERIFY THE VERTICAL AND HORIZONTAL LOCATION OF EXISTING UTILITIES TO AVOID CONFLICTS AND MAINTAIN MINIMUM CLEARANCES. ADJUSTMENT SHALL BE MADE TO THE GRADE OF THE NEW UTILITY AS REQUIRED.
- WATERING:
  - THE TREES WILL REQUIRE SIGNIFICANT WATERING THROUGHOUT THE SUMMER AND EARLY FALL IN ORDER TO SURVIVE LONG-TERM. AN EASY AND ECONOMICAL WATERING CAN BE DONE USING SOAKER HOSES PLACED THREE FEET FROM THE TRUNK OF THE TREE AND SPRAWLED AROUND THE TREE. ONE 75-FOOT SOAKER HOSE FOR TREE IS ADEQUATE. IT IS BEST TO PLACE THE SOAKERS USING LANDSCAPE STAPLES. (AVAILABLE FROM NO FOWLER IN BELLEVUE FOR PENNIES APiece) THEY COVER THE AREA WITH TWO TO THREE INCHES COMPOSTED MATERIALS. THE COMPOSTED MATERIAL WILL ACT AS A MULCH TO MINIMIZE EVAPORATION AND WILL ALSO STIMULATE THE MICROBIAL ACTIVITY OF THE SOIL WHICH IS ANOTHER BENEFIT TO THE HEALTH OF THE TREE.
  - WATER THE TREE TO A DEPTH OF 18 TO 20 INCHES. I RECOMMEND LEAVING THE WATER ON THE SOAKER HOSES FOR SIX TO EIGHT HOURS AND THEN DIGGING DOWN TO DETERMINE HOW DEEP YOUR WATER IS PENETRATING. THEN ADJUST ACCORDINGLY. IT MAY TAKE A GOOD TWO DAYS OF WATERING TO REACH THE PROPER DEPTH.
  - ONCE THE WATER REACHES THE PROPER DEPTH, TURN OFF THE HOSES FOR FOUR DAYS AND THEN WATER AGAIN. WATER MORE OFTEN WHEN TEMPERATURES INCREASE—EVERY THREE DAYS WHEN TEMPERATURES EXCEED 40 DEGREES AND EVERY TWO DAYS WHEN TEMPERATURES EXCEED 50 DEGREES. THIS DRIVING OUT OF THE SOIL IN BETWEEN WATERING IS IMPORTANT TO PREVENT SOIL PATHOGENS FROM ATTACKING THE TREES.

**BLUELINE**  
 SCALE: AS NOTED  
 PROJECT MANAGER:  
 TODD A. OBERG, PE  
 PROJECT ENGINEER:  
 TODD A. OBERG, PE  
 DESIGNER:  
 SAM TURMAN  
 ISSUE DATE:  
 11/20/2017

NO.	DATE	BY	REVISIONS

PRELIMINARY TREE RETENTION  
 PLAN & DETAILS  
 ORCAS MOON COTTAGES  
 PRELIMINARY PLAN / IDP  
 PARCEL #3890100050  
 CITY OF KIRKLAND WASHINGTON

**TREE LEGEND**

- POOR HEALTH/NONVIALE TREE
- EXISTING TREE TO BE REMOVED
- DRIP LINE
- EXISTING TREE TO REMAIN
- EXISTING TREE TO REMAIN BUT BE IMPACTED
- EXISTING OFF-SITE TREE

**UNDERGROUND UTILITY NOTE**  
 UNDERGROUND UTILITIES ARE SHOWN IN THE APPROXIMATE LOCATION. THERE IS NO GUARANTEE THAT ALL UTILITY LINES ARE SHOWN, OR THAT THE LOCATION, SIZE AND MATERIAL IS ACCURATE. THE CONTRACTOR SHALL UNCOVER ALL INDICATED PIPING WHERE CROSSING, INTERFERENCES, OR CONNECTIONS OCCUR PRIOR TO TRENCHING OR EXCAVATION FOR ANY PIPE OR STRUCTURES. TO DETERMINE ACTUAL LOCATION, SIZE AND MATERIAL, THE CONTRACTOR SHALL MAKE THE APPROPRIATE PROVISION FOR PROTECTION OF SAID FACILITIES. THE CONTRACTOR SHALL NOTIFY ONE CALL AT 8-1-1 (WASHINGTON81.COM) AND ARRANGE FOR FIELD LOCATION OF EXISTING FACILITIES BEFORE CONSTRUCTION.

**TREE DENSITY CALCS**  
 REQUIRED (30 CREDITS PER ACRE) 6.44 x 30 = 194 CREDITS REQUIRED  
 PROVIDED 210 CREDITS PROPOSED  
 \*\*ADDITIONAL TREES TO REMAIN NOT SURVEYED OR SHOWN BUT EXIST IN CRITICAL AREA BUFFERS, ACTUAL TREE CREDITS WILL BE HIGHER THAN PROPOSED\*\*

11/20/2017 10:23am User: bobaron  
 C:\Projects\12248\Drawn\12248-16.dwg

Robert Londo, Orcas Moon, LLC  
 RE: Arborist Report at Forbes Creek, TPN 3890100050 & 3890100055.  
 November 20, 2017  
 Page 21 of 21

Attachment No. 5 – Tree Protection Detail

