


Request for clarification regarding location of balcony encroachments relative to the building or ground below. Concerned with balcony water runoff falling within the setback and right of way in particular from 120th St. facing balconies

DESIGN TEAM RESPONSE:

Balcony encroachments along 120th Street repositioned to eliminate the encroachment over the setback and right of way. The balcony projections along Slater fall within the height setback and do not project into the yard or right of way.




FAIRFIELD. carrierjohnson + CULTUR3

Need to provide a canopy location plan.

DESIGN TEAM RESPONSE:


Overhead protection plan provided to show compliance with KZC 105.18 stating at least 75% of building facade shall incude weather protection. Building frontage along 120th street includes 78% covered.



Request for more information related to proposed building materials and their application on the building. Design Team to provide actual samples via a material board and video of materials and/or actual installed examples.

DESIGN TEAM RESPONSE:

Design Team has made available for in person viewing a revised physical materials board as well as a video version. Pages P4 & P5 represent electronic version.



P4

FAIRFIELD. carrierjohnson + CULTUR3

Request for more information related to proposed building materials and their application on the building. Design Team to provide actual samples via a material board and video of materials and/or actual installed examples.

DESIGN TEAM RESPONSE:

Design Team has made available for in person viewing a revised physical materials board as well as a video version. Pages P3 & P4 represent electronic version.



FAIRFIELD. carrier

P5 carrierjohnson + cultura

VIEW ALONG 120TH STREET

Request for more information related to proposed building materials and their application on the building. Design Team to provide actual samples via a material board and video of materials and/or actual installed examples.

City of Kirkland - Slater Mixed-Use Project | January 26, 2021 | content: MATERIALITY CLOSE UP EXHIBIT

DESIGN TEAM RESPONSE:

Renderings have been enhanced to reflect finer grain of proposed materials by including a closer representation of their actual size and layout in the close up images provided. Renderings are also accompanied by photos of actual product applications.



TEXTURED METAL PANEL 1" DEEP STAND-ING SEAMS EVERY 1'-0"



CEMENTITIOUS SMOOTH PANEL REVEALS MAX EVERY 4' X 8'



FLAT METAL PANEL



TEXTURED CERAMIC COATED CLADDING A



TEXTURED CERAMIC COATED CLADDING B

FAIRFIELD.

P6 carrierjohnson + cultura

Comments related to façade design:

- * In general building façades appear flat
- * Additional articulation requested at rear building elevations.
- * Building parapet lines are too repetitive.
- * Building corners are too hard.
- * Slater facing elevation, long linear roof line has no variation.

DESIGN TEAM RESPONSE:

Overall project before and after elevations call out areas further enhanced in response to general facade comments. Pages 11 thru 15 address more specific items.



SOUTH ELEVATION - PREVIOUS



SOUTH ELEVATION - PROPOSED

City of Kirkland - Slater Mixed-Use Project | January 26, 2021 | content: OVERALL ELEVATION

FAIRFIELD. carrierjohnson + cultura

Comments related to façade design:

- * In general building façades appear flat
- * Additional articulation requested at rear building elevations.
- * Building parapet lines are too repetitive.
- * Building corners are too hard.
- * Slater facing elevation, long linear roof line has no variation.

DESIGN TEAM RESPONSE:

Overall project before and after elevations call out areas further enhanced in response to general facade comments. Pages 11 thru 15 address more specific items.



WEST ELEVATION - PREVIOUS



WEST ELEVATION - PROPOSED

P8 FAIRFIELD. carrierjohnson + cultura

Comments related to façade design:

- * In general building façades appear flat
- * Additional articulation requested at rear building elevations.
- * Building parapet lines are too repetitive.
- * Building corners are too hard.
- * Slater facing elevation, long linear roof line has no variation.

DESIGN TEAM RESPONSE:

Overall project before and after elevations call out areas further enhanced in response to general facade comments. Pages 11 thru 15 address more specific items.





NORTH ELEVATION - PROPOSED

P9 FAIRFIELD. carrierjohnson + cultura

Comments related to façade design:

- * In general building façades appear flat
- * Additional articulation requested at rear building elevations.
- * Building parapet lines are too repetitive.
- * Building corners are too hard.
- * Slater facing elevation, long linear roof line has no variation.

DESIGN TEAM RESPONSE:

Overall project before and after elevations call out areas further enhanced in response to general facade comments. Pages 11 thru 15 address more specific items.



EAST ELEVATION - PREVIOUS



EAST ELEVATION - PROPOSED

P10 FAIRFIELD. carrierjohnson + cultura

Comments related to façade design:

- * In general building façades appear flat
- * Additional articulation requested at rear building elevations.
- * Building parapet lines are too repetitive.
- * Building corners are too hard.
- * Slater facing elevation, long linear roof line has no variation.

DESIGN TEAM RESPONSE:


Along NE 120th St. Design Team is confident "E" shaped building configuration resulting in staggered facade planes will not make the elevation appear flat. In addition the inclusion of a drop off/deliveries area along that frontage has further enhanced the articulation of the overall facade. Design Team does not believe further articulation of parapet lines is necessary.





City of Kirkland - Slater Mixed-Use Project | January 26, 2021 | content: BUILDING A REVISIONS





Comments related to façade design:

- * In general building façades appear flat
- * Additional articulation requested at rear building elevations.
- * Building parapet lines are too repetitive.
- * Building corners are too hard.
- * Slater facing elevation, long linear roof line has no variation.


DESIGN TEAM RESPONSE:

At rear elevations additional articulation provided at residential areas by introducing recesses along facade as well as color variations. Added parapet variations at select locations and to highlight roof amenity area at Building B.





City of Kirkland - Slater Mixed-Use Project | January 26, 2021 | content: BUILDING A NORTH ELEVATION REVISIONS





FAIRFIELD. carrierjohnson + CULTUR3

Comments related to façade design:


- * In general building façades appear flat
- * Additional articulation requested at rear building elevations.
- * Building parapet lines are too repetitive.
- * Building corners are too hard.
- * Slater facing elevation, long linear roof line has no variation.

DESIGN TEAM RESPONSE:

At rear elevations additional articulation provided at parking areas by further articulating the proposed garage screen. Additionally, vertical screening elements added which will use similar material as garage screening.









FAIRFIELD.

carrierjohnson + cultura

City of Kirkland - Slater Mixed-Use Project | January 26, 2021 | content: BUILDING A NORTH ELEVATION REVISIONS

Comments related to façade design:

- * In general building façades appear flat
- * Additional articulation requested at rear building elevations.
- * Building parapet lines are too repetitive.
- * Building corners are too hard.
- * Slater facing elevation, long linear roof line has no variation.

DESIGN TEAM RESPONSE:

(1)


(2)

(5)

Variation added along Slater Ave. via use of different shades of color for the proposed linear volumes. Materials scale and layout further represented by including photos of actual product applications as seen on P4 & P5. Additionally, the below wall sections details the horizontal breaks while moving up the building. Thus providing a comfortable pedestrian scale for those walking along the sidewalk.







TYPICAL SECTION ALONG SLATER

FAIRFIELD.

P14 carrierjohnson + cultura

Encouraged Design Team to further study use of white vinyl windows and consider other alternatives.

DESIGN TEAM RESPONSE:

Design Team proposes black vinyl windows at facades readily visible from public right of way and limit use of white vinyl windows to remaining areas.



FAIRFIELD. carrierjohnson + CULTUR3


Update exhibits detailing proposed loading area and trash collection. Need to illustrate the trash bin staging area.

DESIGN TEAM RESPONSE:

Proposed street loading locations have been updated through out the plan set and incorporated in to the design. The trash staging location between Buildings B + C will utilize the same design as the North elevation's garage screening.









City of Kirkland - Slater Mixed-Use Project | January 26, 2021 | content: STREET LOADING AND TRASH STAGING

FAIRFIELD.

P16 carrierjohnson + CULTUR3

Add illustrations to address human scale; example is the wall along west entry drive.

DESIGN TEAM RESPONSE:

Added renderings from a closer angle to show fine grain for the building facades as well as landscape and hardscape features.









FAIRFIELD.

P17 carrierjohnson + cultura

- -Request for further clarification regarding the space behind the building
- -Bollards at the end of our public plaza; possible risk to kids walking into the vehicular travel way
- -Additional detailing of driveway spaces; what are the pedestrian features (designated walkway, seating, planting, etc.)

DESIGN TEAM RESPONSE:

Landscape site plan notes gate locations which limit access to areas behind the building due to safety concerns. Ample lighting as shown on sheet P19 also provided in that area bollards are needed to remain to meet utility company requirements. Landscape site plan notes locations for seat walls, benches, entry stoops to enhance the pedestrian experience.



City of Kirkland - Slater Mixed-Use Project | January 26, 2021 | content: LANDSCAPE SITE PLAN

P18
FAIRFIELD. carrierjohnson + cultura

- -Request for further clarification regarding the space behind the building
- -Bollards at the end of our public plaza; possible risk to kids walking into the vehicular travel way
- -Additional detailing of driveway spaces; what are the pedestrian features (designated walkway, seating, planting, etc.)

DESIGN TEAM RESPONSE:

Landscape site plan notes gate locations which limit access to areas behind the building due to safety concerns. Ample lighting as shown on sheet P19 also provided in that area bollards are needed to remain to meet utility company requirements. Landscape site plan notes locations for seat walls, benches, entry stoops to enhance the pedestrian experience.









AMENITIES LEGEND




MOYE IN / MOVE OUT PARKING



ENHANCED PAVING

STREET VIEW ALONG NE 120TH STREET)

REPRESENTATIONAL IMAGES (SIMILAR)



TERRACED STEPS

STREET ENLARGEMENT ALONG NE 120TH STREET)


FAIRFIELD.

carrierjohnson + CULTUR3

- -Request for further clarification regarding the space behind the building
- -Bollards at the end of our public plaza; possible risk to kids walking into the vehicular travel way
- -Additional detailing of driveway spaces; what are the pedestrian features (designated walkway, seating, planting, etc.)

DESIGN TEAM RESPONSE:

Landscape site plan notes gate locations which limit access to areas behind the building due to safety concerns. Ample lighting as shown on sheet P19 also provided in that area bollards are needed to remain to meet utility company requirements. Landscape site plan notes locations for seat walls, benches, entry stoops to enhance the pedestrian experience.



City of Kirkland - Slater Mixed-Use Project | January 26, 2021 | content: LANDSCAPE SITE PLAN

FAIRFIELD. carrierjohnson + cultura

- -Request for further clarification regarding the space behind the building
- -Bollards at the end of our public plaza; possible risk to kids walking into the vehicular travel way
- -Additional detailing of driveway spaces; what are the pedestrian features (designated walkway, seating, planting, etc.)

DESIGN TEAM RESPONSE:

Landscape site plan notes gate locations which limit access to areas behind the building due to safety concerns. Ample lighting as shown on sheet P19 also provided in that area bollards are needed to remain to meet utility company requirements. Landscape site plan notes locations for seat walls, benches, entry stoops to enhance the pedestrian experience.




STREET VIEW ALONG SLATER AVENUE NE



RAISED PLANTER

REPRESENTATIONAL IMAGES (SIMILAR)



FAIRFIELD. carrierjohnson + cultura