

APPENDIX C

PHOTOGRAPHS

Segment A - PAA



North end of Segment A (PAA), St. Edwards State Park is to the left. Note juxtaposition of native conditions (no armoring, large woody debris, native riparian vegetation) with typical residential condition (bulkhead, pier, lawn with no vegetation overhanging water, no woody debris)



O.O. Denny Park.



Typical boulder bulkhead.



Semi-natural shoreline (emergent vegetation, scattered boulders and gravel beach)

Segment B – Juanita and Yarrow Bays



Juanita Bay – note abandoned piles, nearshore raised boardwalk and abundant shoreline vegetation



Yarrow Bay Wetlands

Segment C – Residential



Waverly Park



Typical shoreline

Segment D – Urban



Kirkland Yacht Club – new breakwater.



Concrete bulkhead in City park..



Carillon Point.



Over-water condominium.