

KIRKLAND POLICE DEPARTMENT TRAFFIC DIVISION

SEP 1 5 2023

CERTIFICATION OF VEHICLE SPEEDOMETER

DATE/TIME: 09-13-2023 at 1010 Hrs. **LIDAR OPERATOR:** Ofc. Spak #364

LOCATION: 11000 Blk of 98th Ave NE

LIDAR UNIT: LTI True Speed S #TJ-009571

VEHICLE OPERATOR: Ofc. Jackson #637 VEHICLE MILEAGE: 92123 POLICE VEHICLE AND VIN: P161 VIN# 1FM5K8AR5HGA24630

P161

ich :

MARIA MARIA

įπ.

On the above date and time while employed by the City of Kirkland, commissioned Police Officer Spak was using the above speed measuring device to certify the speedometer of the above Kirkland Police Department vehicle. The Lidar unit is handheld, optically aimed and used in a stationary position. Officer Spak has been instructed on the use of Lidar speed measuring devices and is qualified to set up, test, and operate this Lidar unit. Training records documenting such are on file with the training unit.

During the certification of the above police vehicle speedometer, Officer Spak was able to isolate the vehicle which was traveling at a constant speed of 30 MPH on the first test and 40 MPH on the second test. The Lidar unit was operating properly and it gave Officer Spak a clear and fast staccato tone, indicating proper aiming of the unit. The Lidar unit then gave a clear and solid "target acquisition" tone. No low battery warning was heard and RFI was not detected.

Officer Spak verified the Lidar unit was operating properly before and after the test by conducting an internal light check, internal circuitry check, and a sight alignment test. Officer Spak also tested the Lidar unit's range capabilities on an established calibrated testing range at the Kirkland Police Department. The tests consist of a "delta distance" test between 50 feet and 75 feet, as well as "fixed distance" tests at 100 feet and 180 feet. These measurements were obtained using a steel tape measure. The above Lidar unit was calibrated by Wescom Communications technician Ed Cole, within the last year. The Lidar calibration certificate is on file with the Kirkland Municipal Court.

The above police vehicle was operated by Officer Jackson, a commissioned Police Officer with the City of Kirkland. Officer Jackson was in radio contact with Officer Spak. At the time that Officer Jackson had the vehicle's speedometer maintained at 30 MPH on the first test, and then 40 MPH on the second test; Officer Jackson notified Officer Spak of such by radio. Officer Spak took a Lidar reading at the moment Officer Jackson gave a verbal notice over the radio. Officer Jackson maintained the constant speed of 30 MPH on the first test and then 40 MPH for the second; each beyond the time required by Officer Spak to obtain an accurate speed reading as noted above.

I certify or declare under penalty of perjury, under the laws of the state of Washington, that the foregoing is true and correct.

Officer: 1 Jacks 14037

637 Date: 09-13-2023

Place: Kirkland, Washington

Officer: 6-58 AL #569

Date: 09-13-2023

Place: Kirkland, Washington

* CORC L TE

Test Speed	LIDAR Speed/Distance	LIDAR Opera (Number and Initi		Vehicle Operator (Number and Initials)	Date
30 mph	30 MPH at 394 feet	#364 65	30 MPH	#637	09-13-2023
40 mph	40 MPH at 357 feet	#364 68	40 MPH	#637	09-13-2023

11750 NE 118th Street, Kirkland, Washington 98034 (425) 587-3400 (TTY Compatible) FAX (425) 587-3423

This document was created by an application that isn't licensed to use <u>novaPDF</u>. Purchase a license to generate PDF files without this notice.

THIS DOCUMENT IS MAINTAINED AS A PUBLIC RECORD IN ACCORDANCE WITH RCW 5.44