



CERTIFICATE CONCERNING DESIGN AND CONSTRUCTION OF ELECTRONIC SPEED MEASURING DEVICES

I, Lesieli Casale, do certify under penalty of the laws of the State of Washington that the following is true and correct:

I have been employed as a technician by American Traffic Solutions for 2 years. I became a speed validation technician on January 12, 2023 and have over 100 hours performing speed validation tests. I am nationally certified as a RADAR and LIDAR operator. The City of Kirkland currently uses the AutoPatrolTM 3D radar fixed speed safety camera system, an electronic speed measuring device provided through a contract with American Traffic Solutions, Inc. ("ATS"). Part of my duties include monitoring regular testing of the AutoPatrol 3D radar fixed speed safety camera systems used by the City of Kirkland.


ATS contracted with the City of Kirkland to provide an Automated Speed Enforcement ("ASE") system designed to record the speed of a vehicle and obtain photographs or other recorded images of the vehicle and the vehicle's registration plate while the vehicle is traveling in excess of speed limits in certain safety zones within posted limits.

The ASE program includes the use of the AutoPatrol 3D radar fixed speed safety camera systems at the following locations within the City of Kirkland:


Location Code	Location Description	Lanes Monitored
KRKF001	NB 132ND AVE NE @ MUIR ELEMENTARY/KAMIAKIN MIDDLE	1
KRKF002	SB 132ND AVE NE @ MUIR ELEMENTARY/KAMIAKIN MIDDLE	1
KRKF003	EB 80TH ST @ ROSE HILL ELEMENTARY	1
KRKF004	WB 80TH ST @ ROSE HILL ELEMENTARY	1
KRKF005	SB 724 STATE ST @ LAKEVIEW ELEMENTARY SCHOOL	1
KRKF006	WB 10600 NE 68TH ST @ LAKEVIEW ELEMENTARY SCHOOL	1
KRKF007	NB 12637 84TH AVE NE @ SANDBURG ES / FINN HILL MS / THOREAU ES	1
KRKF008	SB 14006 84TH AVE NE @ SANDBURG ES / FINN HILL MS / THOREAU ES	1

The AutoPatrol 3D radar fixed speed safety camera system operates by measuring vehicle speed, as well as position relative to the radar to calculate and differentiate multiple vehicles in the radar beam. The speed of a moving vehicle is measured by Doppler radar. Doppler radar is a generally accepted technology used for measuring speed. The AutoPatrol 3D radar technology is used throughout the US and Europe as well as other countries and is approved by the Swiss national metrology institute- METAS.

The AutoPatrol 3D radar fixed speed safety camera system uses a tracking radar sensor for measuring vehicle speeds and detecting speed violations. The AutoPatrol 3D radar is aligned at a fixed angle across the road. The AutoPatrol 3D radar emits a horizontal beam over the road surface as represented by the illustration below. The tracking radar can simultaneously detect multiple vehicles and measure their speed, distance, angle and movement within the radar beam. The radar tracks multiple vehicles by reconstructing vehicle movement from the measured object speed, angle and distance values. If a vehicle passes a defined trigger line, the radar outputs the vehicle's speed and lane information. The camera connected to the tracking radar uses this information to determine if there is a speed violation and to capture photographs showing the measured speed and lane on the databar of the captured images.



The tracking radar utilizes the Doppler Effect for speed determination. If an electromagnetic wave is emitted at a moving object, then the wave is reflected back from the moving object. The frequency of the wave received back by the radar shifts based on the speed of the moving object and its direction of travel. The tracking radar continuously determines this frequency shift of each object to calculate the object's speed. The tracking radar consists of two receiving antennas integrated into a single radar sensor. This configuration allows the radar to measure the distance and angle of the vehicle relative to the position of the radar sensor. Illustration A and B show the measurement principle in simplified form. The radar sensor emits a radar beam (illustration A). The radar beam is reflected by the vehicle (illustration B). The two receivers receive the reflected radar beam. The radar sensor evaluates the return frequency, as well as the phase difference of the reflected radar beam from both of the receivers. With the aid of these values the radar sensor calculates the vehicle position.



Prior to operation each day, the system performs a system self-test. This self-test performs an electronic tuning fork test to produce a specific frequency and returns an associated speed value. Only if the return value meets the acceptance criteria to show that the system is operating correctly will the system enter measure mode. Unless a self-test is successful, the system will not enter measure mode and no violations will be captured. Additional information stored as metadata within each image includes coordinates of the vehicle position at the time of capture. This information is extracted and utilized through a secondary speed verification process to provide yet another means to validate offender speed and position based on the two images obtained and image analytics. In addition to the internal system checks and the manufacturer calibration certification, the 3D radar system is subject to routine and independent calibration check of the speeds produced by the system at least annually by a qualified technician.

Each day the computer which controls the fixed speed safety camera system is rebooted. The reboot is initiated each day and each time the computer is rebooted an internal check is performed on all operations of

each fixed speed safety camera system, including the clocks, sensors, camera and speed calculating hardware and software, in order to verify that all operations are functioning correctly. When the internal check detects a problem with one of the operations on a given fixed speed safety camera system, then that particular fixed speed safety camera system is inactivated and a request for service is relayed to ATS support personnel. This means that violations cannot be issued until any internal problem is fixed.

Speed validation tests are regularly performed on each installed and operable AutoPatrol 3D radar fixed speed safety camera system. The test is conducted by having a LIDAR Operator obtain true measurements of up to five vehicles per lane in the ascending and/or descending direction. The speed of the vehicle is captured by the LIDAR Operator and then relayed via cellular to an ATS Technician. The ATS Technician then compares the vehicle speed measured by the AutoPatrol 3D radar fixed speed safety camera system to the speed measured by the LIDAR Operator to ensure the accuracy of the AutoPatrol 3D radar fixed speed safety camera system. ATS maintains the results of each test in a Validation Report. The speed validation for each system was performed on the following date and the systems at each location were found to be in proper working order:

Location Code	Location Description	Date of Test
KRKF001	NB 132ND AVE NE @ MUIR ELEMENTARY/KAMIAKIN MIDDLE	9/18/2023
KRKF002	SB 132ND AVE NE @ MUIR ELEMENTARY/KAMIAKIN MIDDLE	9/18/2023
KRKF003	EB 80TH ST @ ROSE HILL ELEMENTARY	9/18/2023
KRKF004	WB 80TH ST @ ROSE HILL ELEMENTARY	9/18/2023
KRKF005	SB 724 STATE ST @ LAKEVIEW ELEMENTARY SCHOOL	9/18/2023
KRKF006	WB 10600 NE 68TH ST @ LAKEVIEW ELEMENTARY SCHOOL	9/18/2023
KRKF007	NB 12637 84TH AVE NE @ SANDBURG ES / FINN HILL MS / THOREAU ES	9/18/2023
KRKF008	SB 14006 84TH AVE NE @ SANDBURG ES / FINN HILL MS / THOREAU ES	9/18/2023

Preventative maintenance, including visual inspections, is regularly performed on the AutoPatrol 3D radar fixed speed safety camera systems. Preventative maintenance activities include: cleaning of the cameras and housing, general site inspection of environment and road conditions, inspection of poles, bases and enclosures, and inspection of system cables and connections. The location and date that preventative maintenance is performed is recorded in the Preventative Maintenance Log, which along with the Validation Report(s) referenced above, is attached hereto.

I am a custodian, or otherwise qualified witness, as to the attached records. I make this declaration based on personal knowledge, and if called and sworn as a witness, I could and would testify as set forth in the following paragraph.

Attached as Exhibits are: Exhibit A - Speed Validation Reports, Exhibit B - Preventative Maintenance Logs, and Exhibit C - Annual System Verification Certificate for all AutoPatrol 3D radar fixed speed safety camera systems installed and used by the City of Kirkland. All documents and materials included as Exhibit A, Exhibit B and Exhibit C are authentic and are what they purport to be, and accurately describe the matters set forth therein. All such records are business records in that they are: (1) records kept in the ordinary course of business; (2) created at or near the time of the transactions or events reflected therein by, or based on

information from, a person with knowledge of the transaction or events; and (3) kept as part of a regular business activity.

Based upon my education, training, experience, and knowledge of the AutoPatrol 3D radar fixed speed safety camera system, it is my opinion that the system is so designed and constructed as to accurately employ measurement techniques based on a division of distance over time in such a manner that it will give accurate measurements of the speed of motor vehicles.

I, Lesieli Casale, certify (or declare) under penalty of perjury under the laws of the State of Washington that the foregoing is true and correct.

Dated this 5th day of October 2023 in Mesa, Arizona

Lesieli Casale, Speed Validation Technician

Lesieli Casale



Speed Validation Report Client: Kirkland, WA

Validation Date: September 18, 2023

KRKF001 - NB 132ND AVE NE @ MUIR ELEMENTARY/KAMIAKIN MIDDLE

o Radar Serial Number: 590-113/66806

KRKF002 – SB 132ND AVE NE @ MUIR ELEMENTARY/KAMIAKIN MIDDLE

o Radar Serial Number: 590-113/61513

KRKF003 – EB 80TH ST @ ROSE HILL ELEMENTARY

o Radar Serial Number: 590-113/64095

KRKF004 – WB 80TH ST @ ROSE HILL ELEMENTARY

o Radar Serial Number: 590-113/66135

KRKF005 – SB 724 STATE ST @ LAKEVIEW ELEMENTARY SCHOOL

Radar Serial Number: 590-113/68392

KRKF006 – WB 10600 NE 68TH ST @ LAKEVIEW ELEMENTARY SCHOOL

o Radar Serial Number: 590-113/68391

KRKF007 – NB 12637 84TH AVE NE @ SANDBURG ES / FINN HILL MS / THOREAU ES

o Radar Serial Number: 590-113/68421

KRKF008 – SB 14006 84TH AVE NE @ SANDBURG ES / FINN HILL MS / THOREAU ES

o Radar Serial Number: 590-113/68429

Equipment:

Pro-Lite Plus Hand held Lidar Serial Number: LP05509

Certification Date: October 27, 2022 Lidar Operator: Charles Goodrich RLC Operator: Patricia Hernandez





A speed validation test was conducted for the sites listed above. The Lidar Operator, obtained true measurements of five vehicles per lane in the ascending and/or descending direction. Those speeds were obtained using a Kustom Signals Pro-Lite+ hand held Lidar instrument. The speed of the vehicle is captured by the Lidar Operator and then relayed via cellular to the RLC Technician. The RLC Technician is monitoring the vehicle speed at the Fixed Speed Camera system simultaneously to ensure the accuracy of the system. The speed validation tests performed on the above-listed dates confirmed the accuracy of the Fixed Speed Camera systems at each location.

I, Lesieli Casale, certify that the information contained in this report is true and accurate.

Signed:

Date: October 5, 2023

Mesa, Arizona

American Traffic Solutions Speed Integrity Team

Lesieli Casale



Certificate of Achievement

Speed Integrity Technician Has successfully completed the 16 hour course for

Speed Integrity Technician

This course encompasses all the necessary tasks required to perform the duties as a Speed Integrity Technician. Through this course each participant is required to display the proper competency through written and practical examinations. In addition, this course certifies each participants as a Lidar operator.

Charles Goodrich Presented to:

March 29, 2016 This Day:

Traffic Solutions

Matthew Gloia

Police Truffic Laser/Radar Instructor

an Traffic Soutions, Inc., 7681 East Gray Road, Scottsdale, AZ 85260

Certificate of Achievement

Speed Integrity Technician

Has successfully completed the course for Speed Inegrity Technician

This course encompasses all the necessary tasks required to perform the duties as a Speed Integrity Technician. Through this course each participant is required to display the proper competencies in Radar and Laser Technology. In addition, this course certifies each participants as a Lidar operator.

Patricia Hernandez Presented to:

January 12, 2023 This Day:

American Traffic Solutions"

Tylor Yochim

Tel Vol

DLD Certificate of Achievement V1.0

American Traffic Solutions, Inc., 7681 East Gray Road, Scottsdale, AZ 85260

Certificate # VCC-1022-AZ-07



PB Electronics Inc.

248 W Peaceful Ct., Shepherdsville, KY 40165
502 543-7032 www.pbelectronics.com
Factory Authorized Calibration Center for Stalker, MPH, Kustom, and LTI

Certificate of Calibration

Manufacturer: Kustom

Model: ProLite

Serial Number: LP05509

I hereby certify that this Speed Measuring Device has been checked for accuracy and correctness of operation under my supervision. This Speed Measuring Device is certified accurately within +/- 0.5 mph in stationary mode using equipment traceable to National Institute of Standards and technology.

The laser transmitter of this device has been tested and found to be within specified range for Laser Devices as established by the Federal Communications Commission and IACP.

FCC License number PG-18-12552

Technician Signature



Date: October 27, 2022





SELF-ACCURACY TEST Kustom Signals Pro-Lite+ Lidar Speed Measurement Tool

DATE: September 18, 2023
Start of shift "Self-Diagnostic test" time:9:23 AM
Start of shift Distance check:l00'lidar
End of shift "Self-Diagnostic test" time:11:47 AM
End of shift Distance check:100'
City and State:Kirkland, WA
Lidar Serial Number:LP05509
Certification Date:October 27th, 2022
OPERATOR:Charles Goodrich
I, Charles Goodrich, certify that the Kustom Signals Pro-Lite+ Lidar speed measurement device was setup, tested, and operated in accordance with the manufactures specifications to include its self-diagnostic check.
Further, I certified that the self-check distance was completed and accurate.
Signature: a
Date: September 18, 2023





THE RESERVE OF THE PERSON NAMED IN					
Date	Date			9/18/20	23
Time			11:42 AM		
Site ID				KRKF0	01
Location			K	irkland, Was	hington
Address					ENTARY/KAMIAKIN MIDDLE
Posted Spee	d Limit			20MPI	+
Trigger Spee	ed Limit			26MPI	+
Speed Type				Schoo	1
Lidar Technician			Charles Goodrich		
AutoPatrol Technician			Patricia Hernandez		
Lidar Serial Number			LP05509		
Radar Serial	Number		590-113/66806 Autopatrol-Radar Yes Yes Pass		
Detection Ty	pe				
Measure Mo	de Capture				
Photo enforce	ement sign	is present			
Pass/ Fail					
Ascending o	r Descendir	ng	Descending		ling
City Lane	Times	Lidar Speeds	AP Speeds	Delta	Comments
1	11.42.16	23	23	0	
1	11.42.18	23	23	0	
1	11.42.27	28	27	-1	
1	11.42.29	27	27	0	
1	11.42.34	25	25	0	





		Speed Val	idation Work	sheet	
Date			9/18/2023		
Time				11:40 A	M
Site ID				KRKF0	02
Location				Kirkland,	, WA
Address			SB 132ND AVE NE	@ MUIR ELEM	ENTARY/KAMIAKIN MIDDLE
Posted Spee	d Limit			20MPI	Н
Trigger Spee	ed Limit	1000		26MPI	Н
Speed Type				Schoo	ol
Lidar Techni	cian			Charles Go	odrich
AutoPatrol To	echnician		Patricia Hernandez		
Lidar Serial I	Number		LP05509		
Radar Serial	Number		590-113/61513		
Detection Ty	pe		Autopatrol-Radar		
Measure Mo	de Capture		Yes		
Photo enforce	ement sign	s present	Yes Pass		
Pass/ Fail					
Ascending o	r Descendir	ng	Descending		ding
City Lane Times Lidar Speeds			AP Speeds	Delta	Comments
1	11.40.00	18	17	-1	
1	11.40.02	18	17	-1	
1	11.40.05	17	16	-1	
1	11.40.12	21	22	1	
1	11.40.16	21	22	1	





		Speed Vall	dation work	Sneet	
Date			9/18/2023		
Time			9:28 AM		
Site ID				KRKF0	03
Location			K	irkland, Was	hington
Address			EB 80TH S	T@ROSEH	ILL ELEMENTARY
Posted Spee	d Limit			20MPI	1
Trigger Spee	ed Limit			26MPF	1
Speed Type				Schoo	ı
Lidar Techni	cian			Charles Go	odrich
AutoPatrol To	echnician		Patricia Hernandez		
Lidar Serial N	Number		LP05509		
Radar Serial	Number		590-113/64095		
Detection Ty	pe		Autopatrol-Radar		
Measure Mo	de Capture		Yes Yes Pass		
Photo enforce	ement sign	s present			
Pass/ Fail					
Ascending o	r Descendi	ng		Descend	ing
City Lane	Times	Lidar Speeds	AP Speeds	Delta	Comments
1	09.28.36	16	15	-1	
1	09.29.27	18	18	0	
1	09.29.34	19	18	-1	
1	09.29.38	18	18	0	
1	09.29.56	24	23	-1	





		Speed vall	dation work.	Silect		
Date				9/18/20	23	
Time			9:31 AM			
Site ID				KRKF0	04	
Location			K	irkland, Was	shington	
Address			WB 80TH S	T@ ROSE H	ILL ELEMENTARY	
Posted Spee	d Limit			20MPI	4	
Trigger Spee	ed Limit			26MPI	4	
Speed Type				Schoo	ol .	
Lidar Techni	cian			Charles Go	odrich	
AutoPatrol T	AutoPatrol Technician			Patricia Hernandez		
Lidar Serial I	Number		LP05509			
Radar Serial	Number		590-113/66135			
Detection Ty	pe		Autopatrol-Radar Yes Yes Pass			
Measure Mo	de Capture					
Photo enforce	cement sign	s present				
Pass/ Fail						
Ascending o	r Descendir	ng		Descend	ling	
City Lane	Times	Lidar Speeds	AP Speeds	Delta	Comments	
1	09.31.22	17	18	1		
1	09.32.19	21	22	1		
1	09.32.22	19	19	0		
1	09.32.27	19	19	0		
1	09.37.32	20	20	0		





		Speed Vall	dation work	Sileet	
Date Time				9/18/20	23
			10:01 AM		
Site ID				KRKF0	05
Location			K	irkland, Was	hington
Address			SB 724 STATE S	T@LAKEVIEW	ELEMENTARY SCHOOL
Posted Spee	d Limit			20MPI	4
Trigger Spee	d Limit			26MPI	1
Speed Type Lidar Technician AutoPatrol Technician				Schoo	l
			Charles Goodrich		
			Patricia Hernandez		
Lidar Serial N	lumber		LP05509		
Radar Serial	Number		590-113/68392		
Detection Ty	pe		Autopatrol-Radar Yes Yes Pass		
Measure Mo	de Capture				
Photo enforc	ement sign	s present			
Pass/ Fail					
Ascending o	r Descendir	ng		Descend	ling
City Lane	Times	Lidar Speeds	AP Speeds	Delta	Comments
1	10.01.19	35	35	0	
1	10.01.41	26	26	0	
1	10.01.50	26	26	0	
1	10.03.02	24	24	0	
1	10.03.48	31	31	0	





		Speed Val	idation Works	sheet		
Date				9/18/2	2023	
Time	Time			9:58 AM		
Site ID				KRKF	-006	
Location			K	irkland, W	ashington	
Address			WB 10600 NE 68TH	ST@LAKE	VIEW ELEMENTARY SCHOOL	
Posted Spee	d Limit			20M	PH	
Trigger Speed Limit				26M	PH	
Speed Type			School			
Lidar Technician			Charles Goodrich			
AutoPatrol Te	AutoPatrol Technician			Patricia Hernandez		
Lidar Serial N	lumber			LP05	509	
Radar Serial Number			590-113/68391			
Detection Type			Autopatrol-Radar			
Measure Mode Capture			Yes			
Photo enforcement signs present		Yes				
Pass/ Fail		Pass				
Ascending or	Ascending or Descending			Descending		
City Lane	Times	Lidar Speeds	AP Speeds	Delta	Comments	

City Lane	Times	Lidar Speeds	AP Speeds	Delta	Comments
1	09.58.20	29	30	1	
1	09.59.26	30	31	1	*
1	09.59.37	20	21	1	
1	09.59.41	21	20	-1	
1	09.59.43	20	20	0	





		Speed Vall	uation work	SHEEL	
Date			9/18/2023		
Time			10:19 AM		
Site ID				KRKF0	07
Location			K	irkland, Was	shington
Address			NB 12637 84TH A	VE NE @ SAND THOREAU	BURG ES / FINN HILL MS /
Posted Spee	d Limit			20MPI	H
Trigger Spee	ed Limit			26MPI	4
Speed Type				Schoo	l
Lidar Technician			Charles Goodrich		
AutoPatrol Technician			Patricia Hernandez		
Lidar Serial N	Number		LP05509		
Radar Serial	Number		590-113/68421		
Detection Ty	pe		Autopatrol-Radar		
Measure Mo	de Capture		Yes Yes Pass		
Photo enforce	ement sign	is present			
Pass/ Fail					
Ascending o	r Descendi	ng		Descend	ling
City Lane Times Lidar Speeds		AP Speeds	Delta	Comments	
1	10.19.01	19	19	0	
1	10.19.40	29	30	1	
1	10.22.05	24	24	0	
1	10.22.42	29	29	0	
1	10.24.27	26	26	0	





Speed	Validation	Worksheet
-------	------------	-----------

		Speeu van	illuation worksneet			
Date				9/18/20	23	
Time			10:28 AM			
Site ID	Site ID			KRKF008		
Location			K	irkland, Was	hington	
Address			SB 14006 84TH A	VE NE @ SAND THOREAU	DBURG ES / FINN HILL MS	
Posted Spee	d Limit			20MPI	1	
Trigger Spee	ed Limit			26MPI	4	
Speed Type				Schoo	ol	
Lidar Technician				Charles Go	odrich	
AutoPatrol Technician			Patricia Hernandez			
Lidar Serial I	Number		LP05509			
Radar Serial	Number		590-113/68429			
Detection Ty	pe		Autopatrol-Radar			
Measure Mo	de Capture		Yes			
Photo enforce	ement sign	s present	Yes			
Pass/ Fail				Pass		
Ascending o	r Descendi	ng		Descend	ling	
City Lane	Times	Lidar Speeds	s AP Speeds Delta Comments		Comments	
1	10.28.32	28	28	0		
1	10.28.35	26	26	0		
1	10.28.59	40	39	-1		
1	10.30.24	29	29	0		
1	10.33.56	35	35	0		



1910-071EA-174

Revision:

N/C

Radar Sensor Calibration Verification Certificate of Calibration

Model: RRS24F-ST3

Part Number / Serial Number: 590-113/66806 Ex. 590-XXX / 6XXXX OCT 1 0 2023

MINICIPAL COURT

Description:

Radar Characteristics Validation In compliance with:

RRS24F-ST3 Radar Sensor Calibration Verification Procedure Documentation (5030-0150)

Date of Issue:

January 11, 2023

Owner of EUT:

Verra Mobility

1150 N. Alma School Rd

Mesa, AZ 85201

Attention of:

Engineering Department

Phone: (480) 443-7000

Test Facility			
Test Laboratory	Keystone Compliance, LLC		
Address	131 North Columbus Innerbelt		
City, State, Zip Code	New Castle, PA 16101		
Phone	(724) 657-9940		
Email	emcteam@keystonecompliance.com		
Web Site	www.keystonecompliance.com		

Test Personnel			
Name	Camren Morgan		
Title	EMC Test Engineer		
Signature	Eum my		

CONTROLLED DATA
Properietary and Confidential
Page 15



1910-071EA-174

Revision:

N/C

Radar Sensor Calibration Verification Certificate of Calibration

Model: RRS24F-ST3

Part Number / Serial Number: 590-113/66806 Ex. 590-XXX / 6XXXX

Date of Issue:

January 11, 2023

The frequency measurements performed and recorded within this report demonstrate that the JENOPTIK RR24F-ST3 radar has an accuracy of less than or equal to 0.62 mph in the range of 6.21 mph to 62.14 mph and an accuracy of 0.62 mph to 1.86 mph in the range of 62.14 mph to 186.41 mph. This is equal to or better than +/- 1 mph accuracy up to 100 mph, as specified by the manufacturer.

FSK Frequency Set 1					
Nominal Frequency (GHz)	Measured Frequency (GHz)	Amplitude (dBm)	Frequency Deviation (MHz)	Limit (MHz)	Results
f _o = 24.08	24.078275	17.0778297	-1.72	+/- 48.2	PASS
f ₁ = 24.08725	24.085424	17.3474424	-1.83	+/- 48.2	PASS
f ₂ = 24.089	24.087376	18.3220724	-1.62	+/- 48.2	PASS
$f_3 = 24.09$	24.088351	18.547439	-1.65	+/- 48.2	PASS

FSK Frequency Set 2					
Nominal Frequency (GHz)	Measured Frequency (GHz)	Amplitude (dBm)	Frequency Deviation (MHz)	Limit (MHz)	Results
f _o = 24.12	24.118249	20.6862471	-1.75	+/- 48.2	PASS
f ₁ = 24.12725	24.125725	21.0848535	-1.53	+/- 48.2	PASS
f ₂ = 24.129	24.127351	21.7294888	-1.65	+/- 48.2	PASS
f ₃ = 24.13	24.128326	22.4458445	-1.67	+/- 48.2	PASS

FSK Frequency Set 3					
Nominal Frequency (GHz)	Measured Frequency (GHz)	Amplitude (dBm)	Frequency Deviation (MHz)	Limit (MHz)	Results
f _o = 24.16	24.157901	20.4036356	-2.10	+/- 48.2	PASS
f ₁ = 24.16725	24.16505	21.0372457	-2.20	+/- 48.2	PASS
f ₂ = 24.169	24.167	22.3278755	-2.00	+/- 48.2	PASS
f ₃ = 24.17	24.167975	22.6032364	-2.03	+/- 48.2	PASS

CONTROLLED DATA
Properietary and Confidential
Page 16



1910-071EA-220

Revision:

N/C

Radar Sensor Calibration Verification Certificate of Calibration

FILED
DCT 1 0 2023

Model: RRS24F-ST3

KIRKLAND MUNICIPAL COURT

Part Number / Serial Number: 590-113/61513 Ex. 590-XXX / 6XXXX

Description:

Radar Characteristics Validation In compliance with:

RRS24F-ST3 Radar Sensor Calibration Verification Procedure Documentation (5030-0150)

Date of Issue:

June 19, 2023

Owner of EUT:

Verra Mobility

1150 N. Alma School Rd

Mesa, AZ 85201

Attention of:

Engineering Department

Phone: (480) 443-7000

Test Facility			
Test Laboratory	Keystone Compliance, LLC		
Address	131 North Columbus Innerbelt		
City, State, Zip Code	New Castle, PA 16101		
Phone	(724) 657-9940		
Email	emcteam@keystonecompliance.com		
Web Site	www.keystonecompliance.com		

	Test Personnel
Name	Camren Morgan
Title	EMC Test Engineer
Signature	Erun dry

CONTROLLED DATA
Properietary and Confidential
Page 15



1910-071EA-220

Revision:

N/C

Radar Sensor Calibration Verification Certificate of Calibration

Model: RRS24F-ST3

Part Number / Serial Number: 590-113/61513 Ex. 590-XXX / 6XXXX

Date of Issue:

June 19, 2023

The frequency measurements performed and recorded within this report demonstrate that the JENOPTIK RR24F-ST3 radar has an accuracy of less than or equal to 0.62 mph in the range of 6.21 mph to 62.14 mph and an accuracy of 0.62 mph to 1.86 mph in the range of 62.14 mph to 186.41 mph. This is equal to or better than +/-1 mph accuracy up to 100 mph, as specified by the manufacturer.

	FSK	Frequency Set	1		
Nominal Frequency (GHz)	Measured Frequency (GHz)	Amplitude (dBm)	Frequency Deviation (MHz)	Limit (MHz)	Results
$f_0 = 24.08$	24.077951	1.07583065	-2.05	+/- 48.2	PASS
$f_1 = 24.08725$	24.085101	0.4834434	-2.15	+/- 48.2	PASS
f ₂ = 24.089	24.08705	1.82907643	-1.95	+/- 48.2	PASS
$f_3 = 24.09$	24.088025	1.807434	-1.98	+/- 48.2	PASS

FSK Frequency Set 2					
Nominal Frequency (GHz)	Measured Frequency (GHz)	Amplitude (dBm)	Frequency Deviation (MHz)	Limit (MHz)	Results
f _o = 24.12	24.118575	5.82124907	-1.43	+/- 48.2	PASS
f ₁ = 24.12725	24.125725	5.14385949	-1.53	+/- 48.2	PASS
$f_2 = 24.129$	24.127676	5.90749047	-1.32	+/- 48.2	PASS
f ₃ = 24.13	24.128651	5.66284744	-1.35	+/- 48.2	PASS

	FSK	Frequency Set	3		
Nominal Frequency (GHz)	Measured Frequency (GHz)	Amplitude (dBm)	Frequency Deviation (MHz)	Limit (MHz)	Results
f _o = 24.16	24.158226	4.4716356	-1.77	+/- 48.2	PASS
f ₁ = 24.16725	24.165376	5.84224569	-1.87	+/- 48.2	PASS
f ₂ = 24.169	24.167326	6.93187163	-1.67	+/- 48.2	PASS
$f_3 = 24.17$	24.168301	7.18223101	-1.70	+/- 48.2	PASS





PREVENTIVE MAINTENANCE CHECKLIST

KIRKLAND MUNICIPAL COURT

Date &	Time:	09/22/2023	09:15:00
--------	-------	------------	----------

Site ID: KRKF001

Location: NB 132ND AVE NE @ MUIR ELEMENTARY/KAMIAKIN MIDDLE

Product: AutoPatrol Technician Name: Thomas Yuen See Associated Ticket:

Item	Status	Note/Action (If Status N/A, please specify)
Clean dirt, grime, and graffiti off enclosure and glass.		
1.1. Clean Graffiti. Check physical integrity. Check paint/housing for graffiti and (or) other vandalism.	Pass	
1.2. Clean Glass: Clean and inspect all glass and enclosures.	Pass	
1.3. Clean Enclosure (Interior): Clear vents/fans of obstruction. Remove dust and dirt by vacuum/wiping.	Pass	
1.4. Check Enclosure: If enclosure moved during cleaning, tighten base.	Pass	
Perform a general site inspection to include environmental and road conditions.		
2.1. PLP/Loop Loop: Check for exposed or cut loop wiring, and epoxy wear and tear.	N/A	
2.2. Power & Grounding: Inspect all power and grounding connections.	Pass	
2.3. Radar: Inspect radar and cables. Visually inspect antenna.	Pass	
2.4. WVDs: Check for popped out pucks, visible cracks, or other noticeable damage.	N/A	

3. Inspect poles, bases, and enclosures.		
3.1. Pole:	Pass	
Check sturdiness. Check hurricane collar and confirm screws are tight.		
3.2. Base:	Pass	
Check for cracks. Ensure bolts (and latch bolt) are tight and secure inside base		
3.3. Enclosure:	Pass	
Confirm straps are tight and secure against pole. Tighten if loose.		
4. Inspect cables and connections.		
4.1. Cables:	Pass	
Check all cables for visible wear or damage		
4.2. Connections:	Pass	
Check for exposed wires on pole connecting to radar, camera enclosure, and strobe.	POSSESSES	

5. Take (and attach) photo of enclosure, pole, and photo enforcement sign(s) for presence and damage.





5.1. Enclosure:

5.2. Pole:



5.3. Photo Enforcement Sign(s):





KIRKLAND MUNICIPAL COURT

PREVENTIVE MAINTENANCE CHECKLIST

Date & Time: 09/22/2023 09:19:00	Site ID: KRKF002	Location: SB 132ND AVE NE @ MUIR ELEMENTARY/KAMIA	KIN MIDDLE
Product: AutoPatrol	Technic	ian Name: Thomas Yuen See Asso	ociated Ticket:

ltem .	Status	Note/Action (If Status N/A, please specify)
Clean dirt, grime, and graffiti off enclosure and glass.		
1.1. Clean Graffiti. Check physical integrity. Check paint/housing for graffiti and (or) other vandalism.	Pass	
1.2. Clean Glass: Clean and inspect all glass and enclosures.	Pass	
1.3. Clean Enclosure (Interior): Clear vents/fans of obstruction. Remove dust and dirt by vacuum/wiping.	Pass	
1.4. Check Enclosure: If enclosure moved during cleaning, tighten base.	Pass	
Perform a general site inspection to include environmental and road conditions.		
2.1. PLP/Loop Loop: Check for exposed or cut loop wiring, and epoxy wear and tear.	N/A	
2.2. Power & Grounding: Inspect all power and grounding connections.	Pass	
2.3. Radar: Inspect radar and cables. Visually inspect antenna.	Pass	
2.4. WVDs: Check for popped out pucks, visible cracks, or other noticeable damage.	N/A	

3. Inspect poles, bases, and enclosures.		
3.1. Pole:	Pass	
Check sturdiness. Check hurricane collar and confirm screws are tight.		
3.2. Base:	Pass	
Check for cracks. Ensure bolts (and latch bolt) are tight and secure inside base.		
3.3. Enclosure:	Pass	
Confirm straps are tight and secure against pole. Tighten if loose.		
4. Inspect cables and connections.		
4.1. Cables:	Pass	
Check all cables for visible wear or damage.		
4.2. Connections:	Pass	
Check for exposed wires on pole connecting to radar, camera enclosure, and strobe.		

5. Take (and attach) photo of enclosure, pole, and photo enforcement sign(s) for presence and damage.





5.1. Enclosure:

5.2. Pole:



5.3. Photo Enforcement Sign(s):