

88

Carillon Creek

+4 since 2021



Basin Facts

Basin Area
105.7 acres



Tree Cover
34%





Impervious Area
41%

Water quality: **Some or Low Concern**

A high level of nitrogen is the primary reason this basin did not score higher.



2022 Water Quality



Habitat conditions: Development downstream of Lake Washington Boulevard led to a restoration project on Carillon Creek that reopened channel that was previously piped. The open channel and planted native vegetation have improved fish and wildlife habitat. Cutthroat trout and coho salmon have been found in the lower section of Carillon Creek.

Challenges: Development has significantly increased hard surfaces (pavement and buildings) in the Carillon Creek basin. This impacts the creek's water quality, aquatic habitat, and potential for flooding.

How to Help Nitrogen in Carillon Creek



Minimize fertilizer use in your lawn and garden to reduce nitrogen